## **FGMARCHITECTS**

#### **VILLAGE OF HOFFMAN ESTATES**





## **Village of Hoffman Estates**

Fire Station No. 21 & No. 22 Station Location Analysis, Facility Analysis and Conceptual Design Study

#### **SUBMITTED TO:**

Alan Wax Fire Chief



Fire Station No. 21 225 Flagstaff Ln. Hoffman Estates, Illinois 60169

Phone: 847.843.4825

SUBMITTED BY:

Andy Jasek **FGM** Architects Inc.

1211 West 22<sup>nd</sup> Street, Suite 700

Oak Brook, Illinois 60523 Phone: 630.574.8709

Email: AndyJasek@fgmarchitects.com

Fire Station No. 22 1700 Moon Lake Blvd. Hoffman Estates, Illinois 60169 Phone: 847.843.4825



June 1, 2023

TABLE OF CONTENTS		
SECTION 1	INTRODUCTION	3
SECTION 2	STATION LOCATION ANALYSIS	4
	2.1 EXECUTIVE SUMMARY	5
SECTION 3	EXISTING CONDITIONS	17
	3.1 FIRE STATION No. 21	18
	3.2 FIRE STATION No. 22	19
SECTION 4	SPACE NEEDS ANALYSIS	20
	4.1 FIRE STATION No. 21	21
	4.2 FIRE STATION No. 22	23
	4.3 FIRE DEPARTMENT ADMINISTRATION	26
SECTION 5	EXISTING CONDITIONS REPORT	28
	5.1 FIRE STATION No. 21	28
	5.2 FIRE STATION No. 22	45
SECTION 6	EXISTING CONDITIONS ANALYSIS	60
SECTION 7	POTENTIAL SOLUTIONS	61
	7.1 FIRE STATION No. 21	62
	-CONCEPT A	02
	-CONCEPT B	
	-CONCEPT C	
	-BUDGET	
	7.2 FIRE STATION No. 22	66
	-CONCEPT A	00
	-CONCEPT B	
	-CONCEPT C	
	-BUDGET	
	7.3 FIRE DEPARTMENT ADMINISTRATION	70
	-ANALYSIS	, 0
SECTION 8	CONCLUSION / SUMMARY	71
APPENDIX	ANALYTICS ADDENDUM TO THE STATION LOCATION ANALYSIS	72
	page	s 1-125

#### **SECTION 1**

#### Introduction

Hoffman Estates Fire Department Mission Statement:

TO LIMIT LOSS OF LIFE, INJURY AND PROPERTY DAMAGE TO THE CITIZENS OF HOFFMAN ESTATES BY PROVIDING THE BEST FIRE PROTECTION, ADVANCED LIFE SUPPORT AND EMERGENCY SERVICES IN THE MOST COST-EFFECTIVE MANNER.

In June 2022, the team of FGM Architects and the Illinois Fire Chiefs Association Consulting Team were commissioned to conduct a Station Location Analysis, Facility Analysis and Conceptual Design Study for the Village of Hoffman Estates' Fire Stations No. 21, No. 22 and Fire Department Administration. This study includes an analysis of the geographical location, response area, and quantities of the existing stations, an evaluation of the existing facilities, an analysis of the Fire Department's space needs and a conceptual design study to identify potential solutions for the existing facilities to improve the workflow and efficiency of the Fire Department.

The purpose of evaluating the existing Fire Stations is to review the current building conditions with regards to current Fire service, building codes, space requirements, and facility requirements, as well as current staffing arrangements of the Fire Department and its future growth.

From the findings of the existing facility evaluation and discussions with the Fire Department's staff, a space needs analysis for both Fire Stations No. 21, No. 22 and Fire Department Administration was completed. The space needs analysis compares the existing square footage of the spaces/rooms against the proposed required square footage of the spaces/rooms. The proposed square footages are based on industry standards, code requirements and past project experience. From the findings of the space needs analysis, it was determined that the Fire Department's space needs at both Fire Stations No. 21 & No. 22 exceeds the current space available within the existing buildings. Continuing with a conceptual design provides potential solutions on how best to modify or replace both Fire Stations No. 21 & No. 22 to meet the Fire Department's current and future needs highlighted throughout this study.

The station location analysis uses historical data, "what-if" scenarios, various station location modeling tools, and travel times to best determine where a particular station location should be.

The station facility analysis has been generated by documenting existing conditions through the use of existing floor plans, photographs of existing conditions, and calculating the current square footage of each space. The analysis will illustrate the space deficiencies in the current buildings and the lack of space for each Fire Station. Although the buildings are in fair condition, larger facilities are required to accommodate changes in the fire service and to allow the Fire Department to work more effectively and respond to calls in a timely manner. Enclosed is the documentation of the Fire Department's current working environment and proposed solutions to address the Fire Department's immediate and future facility needs.

This study reinforces the Village of Hoffman Estates' desire to serve its community for many years to come.

#### **SECTION 2**

## **Station Location Analysis** with Predictive Modeling

This section of the report was completed by the Illinois Fire Chiefs Association Consulting Team (IFCA Team). The station location study for the Village of Hoffman Estates (VoHE) is to determine optimal locations for the placement of fire stations in order to select the best location(s) for effective and timely responses. The IFCA Team examined the Hoffman Estates Fire Department's (HEFD) performance, trend analysis alternatives, and future station location(s) possibilities using historical data, "what-if" scenarios, various station location modeling tools, and travel times.

The analytics data for the station location analysis is located at the rear of this report as an appendix labeled **ANALYTICS ADDENDUM.** 



## **Station Location Analysis**

## Hoffman Estates Fire Department

2023

## **EXECUTIVE SUMMARY**







#### **TERMS OF USE**



Illinois Fire Chiefs Association (IFCA) prepared this report which contains confidential and proprietary trade secrets and commercial information of the IFCA and may not be disclosed or republished by anyone other than the client organization. Violation of the confidentiality of this record will cause significant financial harm to the Illinois Fire Chiefs Association.

This report is the copyright of the Illinois Fire Chiefs Association which is protected by State and Federal copyright laws. No part of the document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronically or mechanically, photocopying or scanning this document without prior written permissions of the Illinois Fire Chiefs Association is strictly prohibited. The use, reproduction, downloading or distribution may subject you to the applicable penalties and damages under State and Federal copyright laws.



## **Executive Summary**

The Illinois Fire Chiefs Association Consulting Team (IFCA Team) conducted a Station Location study for the Village of Hoffman Estates (VoHE) to determine optimal locations for the placement of fire stations to select the best location(s) for effective and timely responses. The IFCA Team examined the Hoffman Estates Fire Department's (HEFD) performance, trend analysis alternatives, and future station location(s) possibilities using historical data, "what-if" scenarios, various station location modeling tools, and travel times.

The Team used over three years of historical incident data to measure the agency's emergency services performance and compare it to National Fire Protection Association (NFPA) 1710 standards, Insurance Services Office (ISO) standards, and the Center for Public Safety Excellence (CPSE) recommendations. Using nationally recognized and accepted standards and benchmarks for data collection and analysis, the report findings determined the department's overall baseline system performance to determine the best station location(s).

A Station Location Analysis was conducted to measure the HEFD's emergency response time performance to determine the best station location(s). The delivery of these services commonly originates from fire stations located throughout the area to be protected or within each fire station's Area of Responsibility (AOR). For the response to be effective, crews must respond in a minimum amount of time after the incident has been reported and with the proper resources to mitigate the incident.

Response time performance is a measure that receives a great deal of attention and focus from the community, administrative personnel, and elected officials. It is essential to understand that it is up to the VoHE to determine the service level objectives based on the types of services delivered, reasonable response time for the community, the area served, the resources available, and the risk level the community is willing to accept.


Recommendations in this report relate to HEFD's station locations based on historical data from January 2019 through June 2022.





#### **Jurisdiction Basics and Service Overview**

The IFCA Team analyzed 20,700 incidents from January 2019 through June 2022. The Team identified 19,104 incidents within the Total Response Area (TRA) of the HEFD. EMS-related incidents represented 76.01% of the volume within the HEFD TRA, while 1.14% were classified as fire responses. Other incident types represent the remainder. The analysis also provided insight into the call volume and incident types outside the TRA. There were 1,596 incidents (8.35%) outside the TRA within the study period.



20,700
TOTAL INCIDENTS
19,104
TRA INCIDENTS
1,596
OUTSIDE TRA INCIDENTS

Figure 1: Pg. 32 of the Addendum

#### **Service Area Performance**

HEFD's TRA is 22.6 square miles, protecting a population of 52,462 totaling 18,520 households from four fire stations currently located at 225 Flagstaff Lane (Station 21), 1700 Moon Lake Boulevard (Station 22), 1300 Westbury Drive (Station 23), and 5775 Beacon Point Drive (Station 24) in Hoffman Estates. The Fire Headquarters is located inside the Village Hall at 1900 Hassell Road.



Figure 2: Pg. 4 of the Addendum







Hoffman Estates Fire Department has over 266.4 linear miles of streets within the TRA, and 188 of those linear miles can be reached within a NFPA-recommended 4-minute catchment, which equates to 71% of the TRA.

Of all the incidents HEFD responds to within the TRA, 84% of its calls for service are located within a four-minute catchment (indicated in blue) of the fire stations (calculated based on speed limits of the streets). HEFD's experience consists of arrivals on scenes within 4 minutes, 74% of the time for fire incidents, and 82% for EMS within the 4-minute catchments. Actual arrivals for the entire TRA are 63% of the time for fire incidents and 73% for EMS incidents.





Figure 4: Pg 63 of the Addendum





### Station 21



Station 21 has an Area of Responsibility (AOR) of 3.7 square miles covering a population of 17,473, totaling 6,047 households. Station 21 responded to 5,462 incidents within its AOR, which equates to 29% of the total calls within the study period. HEFD Station 21 has over 63.6 linear miles of streets within its response area, and 47.4 of those linear miles can be reached within a 4-minute catchment equaling 74% of its AOR.



Figure 5: Pg 46 of the Addendum

### Station 22

Station 22 has an Area of Responsibility (AOR) of 9.8 square miles covering a population of 16,459, totaling 6,117 households. Station 22 responded to 9,406 incidents within its AOR, which equates to 49% of the total calls within the study period. HEFD Station 22 has over 82.4 linear miles of streets within its response area, and 55.4 of those linear miles can be reached within a 4-minute catchment equaling 67% of its AOR.









Figure 6: Pg 47 of the Addendum



Page 10



#### Station 23



Station 23 has an Area of Responsibility (AOR) of 3.0 square miles covering a population of 13,474, totaling 4,618 households. Station 23 responded to 2,145 incidents within its AOR, which equates to 11% of the total calls within the study period. HEFD Station 23 has over 51.2 linear miles of streets within its response area, and 39.6 of those linear miles can be reached within a 4-minute catchment equaling 77% of its AOR.





## Station 24

Station 24 has an Area of Responsibility (AOR) of 6.1 square miles covering a population of 5,057, totaling 1,738 households. Station 24 responded to 2,077 incidents within its AOR, which equates to 11% of the total calls within the study period. HEFD Station 24 has over 69.3 linear miles of streets within its response area, and 37.3 of those linear miles can be reached within a 4-minute catchment equaling 54% of its AOR.








Figure 8: Pg 49 of the Addendum





#### **Station Location**


The IFCA Team applied analytic modeling tools to identify ideal station locations for the TRA to achieve the most efficient overall performance. A series of "what-if" scenarios were created to determine the best placement of the stations. The <u>Allocation Analysis</u> tool provided 640 possible fire station locations utilizing a 4-minute drive time as the limit to determine the ideal station location. The analysis of HEFD's performance data over the three-and-a-half-year study period allowed the IFCA Team to develop numerous separate and distinct scenarios to determine the best station location(s), including Ideal Station Locations with current conditions, as well as growth scenarios with In Progress, High Likelihood, and Low Likelihood development. Options with 3-station and 5-station configurations were also analyzed, however shortcomings identified did not make those viable, and thus they are not presented here.

#### **Ideal Station Location**

Ideal Station Location configures the best station location(s) within HEFD's TRA. In this scenario, the IFCA Team removes all existing Fire Stations from the HEFD TRA and reconfigures the stations utilizing historical data to provide new fire station locations that would best serve the community. Although the IFCA Team realizes these models are extreme, they offer an excellent snapshot of the best station placement configurations. These models help visualize a best-case response scenario to the community founded on analytics.

Under the Ideal Stations section in the report, HEFD's current fire station configuration is very close to the modeling of each ideal station location configuration. Currently, HEFD station locations cover 84% of all incidents within 4 minutes. By relocating all current fire stations to ideal locations, there is a 3% increase in the number of incidents within the 4-minute catchments (from 84% to 87%).

Including in-progress and high-likelihood development projects in the calculation results in the number of incidents within the 4-minute catchments from ideal station locations increasing to 88%. (Addendum pages 96 & 97



Reminder: The station location scenarios are based on historical incident data over three-and-a-half years. The software that creates these scenarios locates stations in the best location to respond to these incidents. Relocating the stations to different areas within the AOR also affects the response outcomes of each scenario in the TRA. Furthermore, if HEFD decides to relocate fire stations to identified parcels or new parcels, AOR boundaries may need to be evaluated and adjusted to reflect a new location for maximum incident coverage.





#### **Auto-Aid Impact**

Automatic aid impact models were configured (pages 106-125) to illustrate the percentage of incidents a neighboring fire department station can reach within 8 minutes of travel time inside of the boundaries of HEFD. Although automatic/mutual aid from another agency's fire station cannot be guaranteed, the models show varying levels of support from surrounding fire stations. Schaumburg Fire Stations 51, 52, 54, and Streamwood Station 33 can considerably impact responding to incidents for/with Hoffman Estates in AOR 21 and AOR 22. Palatine Rural (Inverness) Fire District substantially affects Hoffman Estates AOR 23. (Full graphics/maps are included on pgs. 106-125 of Addendum)

Continuing to utilize or create automatic aid agreements with all neighboring agencies for augmentation and first responding (when Hoffman Estates' apparatus is committed or will endure long travel times to incidents) is recommended.




Figure 11: Pg 117 of the Addendum




Figure 13: Pg 120 of the Addendum




Figure 12: Pg 118 of the Addendum




Figure 14: Pg 124 of the Addendum





#### Recommendations

System reliability incorporates time and distance from the resource to the incident, along with the availability and capability of the resources. When reviewing the data analytics and the overall system performance, the IFCA Team believes that station location, multiple incidents, and the number of resources to mitigate the incidents impact a timely response. Any improvement in these areas will benefit the calls for service performance.

The IFCA Team creates recommendations based on the incident data, travel times, incidents covered within the catchment areas, ideal station locations, growth impact, etc. Further considerations should be evaluated beyond the data-driven recommendations. Increases in coverage would only be realized within these recommendations by moving the station(s) to a new location(s) based on the models presented. The VoHE should consider the impact of moving a station, including site availability and feasibility, site costs, construction costs, staffing, equipment, etc., that are not included in the data analysis.

It is up to the VoHE to determine fire station distribution based on the following:


- The level of incident coverage desired
- The response goals set by the agency and its elected officials
- Financial considerations and budget impact
- FGMA report on facility analysis (remodel or rebuild scenarios).

#### **Recommendation 1**

#### Fire Station 21 Relocation to 411 West Higgins

HEFD's current four-stations locations are geographically located in excellent locations based on historical performance, projected performance, and current and projected community development. Relocating Stations 21, 22, 23, and 24 to the Ideal Locations will not realize enough improvement in incidents covered and response times to support and justify the financial impact of relocating these fire

stations. However, if the Fire Station Facilities Analysis report reveals a need for Station 21 to be substantially remodeled, upgraded, or replaced, relocating this station to 411 West Higgins would be the best choice. This property location increases the number of incidents within the four-minute catchment from 84% to 86%. The relocation would improve the level of service provided by increasing the ability to reach more incidents within the catchment area and meet the objective of replacing an aging fire station by constructing a new modern facility.








#### **Recommendation 2**

#### Fire Station 22 Relocation to Identified Ideal Station Location Area


If the Facilities Analysis report revealed that Station 22 was in a condition where relocation was a more cost-effective option than remodeling, then constructing a new modern fire station in the identified Ideal station location area would be advisable. **This relocation would <u>maintain</u> the organization's 4-minute catchment of 84%.** 

These recommendations to relocate or remodel Station 21 and Station 22 rely heavily on the Facilities Analysis Report. It will be the responsibility of the Village officials to determine the cost-benefit of remodeling versus relocating (building new). Additionally, site analyses must be completed before selecting the best option for potential fire station locations.



#### **Additional Models**

Additional model analytics were processed to determine the effectiveness of relocating HEFD Stations 21 (to 411 W Higgins) and 22 (to the identified Ideal station location area). In the current configuration, there would be the potential to realize a 1% increase within the TRA 4-minute catchment area. Overlaying the in-progress and highly likely growth projections, the incidents within the TRA 4-minute catchment would remain statistically unchanged from the current station locations (84%). The cost-benefit factor of building two new fire stations over a remodeling strategy is not advised based only on



the minimal gains in service.

However, if funding was available and it coincided with the facilities analysis to move both stations, the Village should further consider this option as it addresses the objectives of upgrading facilities and improving service performance, even though it is minimal.





### **Supporting Information: Configuration of Fire Stations to Select Parcels**

Several models were configured to relocate fire stations based on Village-owned or identified properties in specific AOR's.

- Station 22 to the identified ideal station location area
- Station 22 to the identified alternate station location site
- Station 21 to 411 West Higgins

Station	New Parcel Location	Current Percent Incidents Reached in 4 minutes Total TRA	Proposed Move Percent Incidents Reached in 4 minutes Total TRA	Percent Change TRA	Estimate Number of Potential incidents reached (+ or -) annually in TRA
Station 21	411 West Higgins	84%	86%	+2%	109
Station 22	Identified Ideal Location Area	84%	84%	0%	-
Station 22	Identified Alternate Location Site	84%	82%	-2%	104

Calculations are based on data contained in the report.



#### **SECTION 3**

## Station No. 21, No. 22 Existing Conditions

#### **Description of Fire Station No. 21:**

Fire Station No. 21 located at 225 Flagstaff Lane was originally built in 1960. A fitness and locker room addition was constructed in the 1990's. The original building and addition were constructed of CMU masonry bearing walls clad with veneer brick. The existing membrane roof over the apparatus bays are pitched and supported by structural steel joists. The existing membrane roof over the residence wings are flat and supported by structural steel joists. The interior walls at this station are primarily CMU block partitions in the apparatus bay, bay support and residence areas.

Fire Station No. 21 is a satellite station for the Fire Department. The vehicles housed at this fire station include (1) Engine, (1) Medic, (1) Reserve Engine, and (1) Reserve Medic.

Fire Station No. 21 is located in a residential neighborhood adjacent to a church, school and park. The station is located South of Higgins Rd. off of Roselle Rd. The fire apparatus discharge directly onto Flagstaff Lane. Station No. 21 has a concrete apron with asphalt drives and parking lot.

#### **Description of Fire Station No. 22:**

Fire Station No. 22 located at 1700 Moon Lake Boulevard was originally built in the 1970s. The existing building is a single-story facility with a basement. The first floor above the basement is precast concrete planks. Exterior walls are constructed of uninsulated single wythe masonry bearing walls. The existing ballasted membrane roof over the apparatus bays, bay support and residence are flat and supported by structural steel joists. The interior walls at this station are primarily CMU block partitions in the apparatus bay, bay support and residence areas.

Fire Station No. 22 is the central station for the Fire Department. The vehicles housed at this fire station include (1) Engine, (1) Squad, (1) Ladder truck, (1) Medic, and the shift commander vehicle.

Fire Station No. 22 is located in a commercial area adjacent to the medical facilities and retail. The Station is located South of Higgins Rd. The fire apparatus discharge directly onto Moon Lake Boulevard. Station No.22 has a concrete apron with asphalt drives and parking lot.

#### **Description of Fire Department Administration:**

Fire Administration is located on the second floor of the Village Hall at 1900 Hassell Road. The department is contained within their own "suite" and includes the Fire Chief, (2) Deputies, a Battalion Chief, (1) administrator, and fire prevention staff.


### **SECTION 3.1**

### Station No. 21

## **Existing Floor Plan Diagram**

Ground Floor Gross Area: 6,175 sq.ft.

Ground Floor Net Area: 5,472 sq.ft.



MAIN LEVEL FLOOR PLAN SCALE: 1/16" = 1' -0"

Note:

Gross Area: The area of the entire floor plate

including all walls

Net Area: The usable area not including wall

thicknesses, chases and shafts




#### **SECTION 3.2**

## Station No. 22 **Existing Floor Plan Diagram**

(Note: Room designations and uses are shown as existed following construction, before remodeling that occurred several years ago)

**Basement Floor Gross Area:** 3,418 sq.ft.


**Basement Floor Net Area:** 3,083 sq.ft.



LOWER LEVEL FLOOR PLAN SCALE: 1/16" = 1'-0"

First Floor Gross Area: 8,116 sq.ft.

First Floor Net Area: 7,493 sq.ft.



Note:

Gross Area: The area of the entire floor plate

including all walls

Net Area: The usable area not including wall

thicknesses, chases and shafts

MAIN LEVEL FLOOR PLAN SCALE: 1/16" = 1' -0"





Fire Station No. 21 & No. 22 Study

#### **SECTION 4**

Station No. 21, No. 22 & Fire Department Administration Space Needs Analysis

#### **Space Needs Analysis**

The Space Needs Analysis evaluates the Fire Department's current space usage and what their anticipated needs will be in the future at both Fire Station No. 21., No. 22 and the Fire Department Administration. The process begins by FGMA sending the fire department a pre-meeting questionnaire in order to prepare the group for the topics of discussion. Then a meeting takes place between FGMA and Fire Department representatives to thoroughly review each station room by room and discuss the current operations versus the anticipated needs.

The programs are developed with the input of the Fire Department taking into consideration their current uses, needs, and operations. Room and space sizes are based upon NFPA guidelines, typical size standards and FGMA's extensive fire station design expertise.

For the Hoffman Estates Fire Department, the difference between current conditions and proposed is substantial for both stations. Part of this need is immediate in nature as the substantial deficits are felt in the current operations and uses. The other shortcomings are trying to anticipate the future of the fire service and prepare to have space when the department grows and changes.

Several areas within the current stations do not meet NFPA guidelines and do not provide proper clearances around equipment being stored on the bay floor. Providing adequate space around equipment and keeping a clear bay floor promotes safety and helps to ensure a safe route for responders to vehicles.

The Fire Department administration is currently located on the second floor of the Village Hall. The comparison between the current conditions and proposed needs is a little more difficult to compare. This is due to the fact that the administration located in the village hall currently shares common space within the building such as bathrooms, break areas, entrance ways and lobbies, and general building infrastructure elements. The actual offices and rooms within the administrative area are for the most part sized correctly. If the administration were to be relocated to one of the fire stations, it may or may not be able to share some of the common building elements as it currently does in Village Hall. It was noted that there is not a need for additional space for other functions at the Village Hall so the relocation would be solely based on the operational desires of the Fire Department to move to one of the fire stations.

Please see the Space Needs Programs on the following pages.





## **Village of Hoffman Estates**

Fire Station No. 21, 22, & Administration

Fire Station No. 21

## **FGMA**RCHITECTS

		Existing Area	Proposed Area	
	Space Description/Room	(Sq. Ft.)	(Sq. Ft.)	Notes/Comments
Public	С			
1.0	Entry Vestibule	93	70	
2.0	Lobby/ Department Tradition	-	100	
3.0	Firefighter Resiliency/ Mothers Room	-	80	(1) mothers, PTSD manage, stress manage, diabetes manage, etc. Per IL law, mothers room to be provided, and wellness room recommended per NFPA
4.0	Public - Single User Restroom - 1	-	80	(1) WC, (1) lav - constructed as storm shelter
	Sub-Total	93	330	
	15% Circulation Factor		50	area % req'd for corridors & access
	PUBLIC TOTAL	93	380	Net Sq. Ft.
Admi	nistration			
				(2) workstations, (2) guest chairs, (3) closets, officer
1.0	Officer Office	168	200	bunk in main bunk room
				adjacent to bays. (3) workstations, (2) printers, laid out
2.0	Firefighter Office	-	400	to have central conference table for training.
	Sub-Total	168	600	
	25% Circulation Factor	-	150	area % req'd for corridors & access
	ADMINISTRATION TOTAL	168	750	Net Sq. Ft.
Resid	ential			
1.0	Dayroom - 7	700	450	Greatroom concept
				(3) fridges, (1) comm stove, (1) deep sink, (1) ADA sink, (1) microwave, (1) high end dishwasher (miele), ice/fill
2.0	Kitchen - 7	inc in dayroom	220	station, coffee, possible pot rack
3.0	Dining Room - 7	inc in dayroom	140	
4.0	Kitchen Pantry	63	100	(3) shift pantry closet, (1) common supply closet
5.0	Bunkrooms - 7	444	630	90 SF - bed, desk, (3) small lockers for bedding, door, walls to ceiling.
6.0	Mens Toilet/ Shower Room	184	-	
7.0	Womens Toilet/ Shower Room	223	-	
8.0	Single User Restrooms	-	300	Provide (3) rooms, with (1) WC, (1) sink and (1) shower
9.0	Universal Locker Room	-	480	(24) lockers, (2) sinks
				free weights, cardio equipment, stretching area,
10.0	Fitness Room	380	500	resistence training
11.0	Janitor Closet/Supplies	47	50	
12.0	Residential Laundry	-	100	washer, dryer, supplies, storage
	Sub-Total Sub-Total	2,041	2,970	
	20% Circulation Factor	-	594	area % req'd for corridors & access
	RESIDENTIAL TOTAL	2,041	3,564	Net Sq. Ft.





## **Village of Hoffman Estates**

Fire Station No. 21, 22, & Administration

Fire Station No. 21

## **FGMA**RCHITECTS

Space Description/Room  (Sq. Pt.)  Notes/Comments  (2) 20 W x 85'L & (1) middle 17'W x 85'L - drive thru bays - engine, medic, reserve engine, reserve medic control of the part of the space of the part o			Existing Area	Proposed Area	
D. Apparatus Area  1. 0 Apparatus Bays - (3) Bays 2,744 4,845 Screen doors on bay with sectional Olf doors. 2. 0 Turnout Gear Lockers on bay floor 480 of gear, negative pressure of gear negative pressure value of gear negative pressure side of gear negative pressure of gear neg		Space Description/Room	•	•	Notes/Comments
1.0   Apparatus Bays - (3) Bays   2,744   4,845   Screen doors on bays with sectional Orl doors.	D Anna	1 -	(54.11.)	(54.11.)	Notes/ Comments
1.0 Apparatus Bays - (3) Bays 2, 2744 4,845 Says-cene doors on bays with sectional Oil doors.  2.0 Turnout Gear Lockers on bay floor 480 (24) sets of open rack lockers & open shelves for 2nd set of gear, negative pressure (14) Large Extractor, with sectional Oil doors.  3.0 Bay Laundry 42 180 of gear, negative pressure (14) Large Extractor, with self-diver, slop sink, drying closet/cabinet, etc. Look at possibility of installing a lift on bay floor to rate for drying.  4.0 Decon/EMS Dirty inc in bay laundry 120 shower, boot was for drying.  5.0 EMS Supply 38 25 small close for drying.  6.0 Work Room/ Tools/ Equipment 60 150 toolbox, work bench, spare parts storage, air compressor 7.0 Toilet 22 80 (1) WC, (1) av, (1) shower (1)	ъ. прри	Tuttus Arcu			(2) 20'W x 85'L & (1) middle 17'W x 85'L - drive thru
2.0 Turnout Gear Lockers on bay floor dependence of page, negative pressure of page, negative pressure (i) large Extracts washer driver, slop sink, drying close/Cabinet, etc. Look at possibility of installing a lift on bay floor to raise hose for drying.  4.0 Decon/EMS Dirty inc in bay laundry 120 in bay floor to raise hose for drying.  5.0 EMS Supply 38 25 small closes for supplies and the supplies of the supp					
2.0   Turnout Gear Lockers	1.0	Apparatus Bays - (3) Bays	2,744	4,845	Screen doors on bays with sectional OH doors.
3.0 Bay Laundry 42 180 (1) Large Extractor, washer/dryer, slop sink, drying closed to possibility of installing a lift on bay load to possibility of installing a lift on bay load to possibility of installing a lift on bay load to possibility of installing a lift on bay load to possibility of installing a lift on bay load to to raise hose for drying.  4.0 Decon/EMS Dirty inc in bay laundry 120 shower, book to show, book possibility of installing a lift on bay load to possibility of installing a lift on bay load to possibility of installing a lift on bay load to possibility of installing a lift on bay load to possibility of installing a lift on bay load to possibility of installing a lift on bay load to possibility of installing a lift on bay load to possibility of installing a lift on bay load to possibility of installing a lift on bay load to possibility of installing a lift on bay load to possibility of installing a lift on bay load to possibility of installing a lift on bay load to possibility of installing a lift on bay load to possibility of installing a lift on bay load to possibility of installing a lift on bay load to possibility of installing a lift on bay load to possible with sideboards, statl decon shower, showed, before shower, showed, before storage, air compressor 10.0 loaded to confort four pumps parts storage, air compressor 10.0 loaded on confortant promises of					(24) sets of open rack lockers & open shelves for 2nd set
3.0 Bay Laundry 42 180 closer/cabinet, etc. Look at possibility of installing a lift on bay laundry (1) becon/EMS Dirty inc in bay laundry 120 shower, boot wash (1) becon/EMS Dirty 38 25 small closer for supplies 50.0 EMS Supply 38 25 small closer for supplies 5 small closer 5 small small state 6 small	2.0	Turnout Gear Lockers	on bay floor	480	of gear, negative pressure
3.0 Bay Laundry 42 180 on bay floor to raise hose for drying.  4.0 Decon/EMS Dirty inc in bay laundry 120 shower, boot wash shower boo					(1) Large Extractor, washer/dryer, slop sink, drying
4.0 Decon/EMS Dirty inc in bay laundry 120 shower, boot wash 5.0 EMS Supply 38 25 small coset for supplies 5.0 EMS Supply 38 25 small coset for supplies 5.0 EMS Supply 38 25 small coset for supplies 5.0 EMS Supply 5.					closet/cabinet, etc. Look at possibility of installing a lift
4.0 Decon/EMS Dirty inc in bay laundry 5.0 EMS Supply 38 25 small closer to supplies 6.0 Work Room/Tools/ Equipment 60 150 toolbox, work bench, spare parts storage, air compressor 7.0 Toilet 22 80 (1) WC, (1) av, (1) av, (1) shower 8.0 Hospital Storage 9.0 Chargers/Mail Alcove 45 90 located on corridor/ramp from house to bays. 10.0 Bay Storage 1 10.0 Bay Storage 1 10.0 general equipment storage 11.0 Seasonal Storage 1 10.0 general equipment storage 11.0 Seasonal Storage 1 10.0 general equipment storage 11.0 Seasonal Storage 1 10.0 Seasonal Storage 1 10.0 Mechanical Room 2.951 6,154 5% Circulation Factor - 308 area % req'd for corridors & access NAPARATUS AREA TOTAL 2.951 6,462 Net Sq. Ft.  E. Support/Storage 1 14 140 switchcape needs 1 14 140 switchgar needs 1 15 15 16 RTUs with control s system, HW heater, boiler, pumps, etc. 1 14 140 switchgar needs 1 15 15 16 Stairs 1 15 Stai	3.0	Bay Laundry	42	180	on bay floor to raise hose for drying.
5.0   EMS Supply   38   25   small closet for supplies					(1) st.stl scullery sink with sideboards, st.stl. decon
6.0 Work Room/Tools/ Equipment 60 150 toolbox, work bench, spare parts storage, air compressor 7.0 Toilet 22 80 (1) Wc, (1) lav, (1) shower 8.0 Hose Storage inc in bay laundry 20 aloxed on corridor/ramp from house to bays. 9.0 Chargers/Mail Alcove 45 90 located on corridor/ramp from house to bays. 10.0 Bay Storage - 100 general equipment storage 11.0 Seasonal Storage inc in workroom 64 showshower, salt, weedwacker, shovels, etc.	***************************************		inc in bay laundry		shower, boot wash
7.0 Toilet 22 80 (1) WC, (1) lav, (1) shower 8.0 Hose Storage inc in bay laundry 20 alcove off or bay floor 9.0 Chargers/Mail Alcove 45 90 located on corridor/ramp from house to bays. 10.0 Bay Storage - 100 general equipment storage 11.0 Seasonal Storage inc in workroom 64 snowblower, salt, weedwacker, shovels, etc.  Sub-Total 2,951 6,154 6,154 6,154 6,165	5.0				small closet for supplies
8.0 Hose Storage inc in bay laundry 20 alcove off of bay floor 9.0 Chargers/Mail Alcove 45 9.0 located on corridor/ramp from house to bays. 10.0 Bay Storage - 10.0 general equipment storage 11.0 Seasonal Storage inc in workroom 64 snowblower, salt, weedwacker, shovels, etc.  Sub-Total 2,951 6,154 6,462 APPARATUS AREA TOTAL 2,951 6,462 Net 5q. Ft.  E. Support/Storage  1.0 Mechanical Room 105 150 RTUs with control's system, HW heater, boiler, pumps, etc MDP, ATS, panels, room for future charging power switchgar needs (1) rack - cameras, remote access, alerting, phones, etc., space for additional (1) rack - cameras, remote access, alerting, phones, etc., space for additional (1) rack incoming water service, fire suppression piping, etc. 1.0 Stairs - Assumed single story  8.0 Emergency Generator 0 - Assumed single story  Sub-Total Rooms 129 580 area % req'd for corridors & access Net 5q. Ft.  Sub-Total Net Building Area ReQuireD 6,175 13,562 Gross Sq. Ft.  Exterior Space ReQuireMents  Parking, TOTAL Public Parking 12 4 Foliouple actions of the parking of the public Parking 12 14 7, double at shift change Outdoor Patio	***************************************				toolbox, work bench, spare parts storage, air compressor
9.0   Chargers/Mail Alcove   45   90   located on corridor/ramp from house to bays.   10.0   Bay Storage   -   100   general equipment storage					(1) WC, (1) lav, (1) shower
10.0 Bay Storage inc in work on 64 snowblower, salt, weedwacker, shovels, etc.    Sub-Total   2,951   6,154     Sweedwacker, shovels, etc.   308	000000000000000000000000000000000000000				
Seasonal Storage   Inc in workroom   64   Snowblower, salt, weedwacker, shovels, etc.			45		
Sub-Total 5% Circulation Factor APPARATUS AREA TOTAL 2,951 6,462 Net Sq. Ft.  E. Support/Storage 1.0 Mechanical Room 105 150 RTUs with control s system, HW heater, boiler, pumps, etc. MDP, ATS, panels, room for future charging power switchgear needs (1) rack - cameras, remote access, alerting, phones, etc., space for additional (1) rack 4.0 Water Service/Sprinkler inc in elect 90 space for additional (1) rack 4.0 Water Service/Sprinkler inc in mech 80 incoming water service, fire suppression piping, etc. 5.0 General Building Storage 120 6.0 Stairs Assumed single story 8.0 Emergency Generator 0 - Exterior  Sub-Total 10% Circulation Factor - 58 SUPPORT/STORAGE TOTAL 219 638 Net Sq. Ft.  Sub-total Net Building Area 15% Grossing Factor - 1,769 TOTAL GROSS BUILDING AREA REQUIRED EXTERIOR SPACE NEED REQUIREMENTS Parking, TOTAL Public Parking 2 4 Staff Parking 12 14 7, double at shift change Small area for grill and seating.			_		
Sweet   Swee	11.0				snowblower, salt, weedwacker, shovels, etc.
E. Support/Storage  1.0 Mechanical Room 105 150 RTUs with control s system, HW heater, boiler, pumps, etc.  2.0 Electrical Service 114 140 switchgear needs  3.0 I.T. Room inc in elect 90 space for additional (1) rack space for					
E. Support/Storage  1.0 Mechanical Room  1.0 MoP, ATS, panels, room for future charging power switchgear needs  (1) rack - cameras, remote access, alerting, phones, etc., space for additional (1) rack  1.0 Water Service/Sprinkler  1.0 Methanical Room  1.0 Water Service/Sprinkler  1.0 General Building Storage  1.0 Incoming water service, fire suppression piping, etc.  1.0 Elevator  1.0 Elevator  1.0 Elevator  1.0 Emergency Generator  1.0 Emergency Generator  1.0 Emergency Generator  1.0 Exterior  1.0 Sub-Total  1.0 Sub-Total  1.0 Sub-Total  1.0 Sub-Total  1.0 Sub-Total  1.0 Sub-Total  1.0 Griculation Factor  1.0 Samultaing Area  1.0 Sub-Total Rooss Building Area  1.0 Sub-Total Rooss Building Area  1.0 Sub-Total  1.0 Sub-Total Rooss Building Area  1.0 Sub-Total Rooss Building Area  1.0 Sub-Total  1.0 Sub-Total Rooss Building Area  1.0 Sub-Total  1.0 Sub-Total Rooss Building Area  1.0 Sub-Total  1.0 Sub-Total Rooss Building Area  1.0 Sub-Total Rooss Building Area  1.0 Sub-Total  1.0 Sub-Total Rooss Building Area  1.0 Sub-Total  1.0 Sub-Total Rooss Building Area  1.0 Sub-Total Rooss Sullange Area  1.0 Sub-Total  1.0 Sub-Total Rooss Sullange Area  1.0 Sub-To					
1.0 Mechanical Room  1.0 Mechanical Room  2.0 Electrical Service  1.14 140		APPARATUS AREA TOTAL	2,951	6,462	Net Sq. Ft.
1.0 Mechanical Room  1.0 Mechanical Room  2.0 Electrical Service  1.14 140	F 6	ant (Channa			
2.0 Electrical Service 114 140 switchgear needs switchgear needs (1) rack - cameras, remote access, alerting, phones, etc., space for additional (1) rack - cameras, remote access, alerting, phones, etc., space for additional (1) rack - cameras, remote access, alerting, phones, etc., space for additional (1) rack incoming water service, fire suppression piping, etc.  5.0 General Building Storage 120 6.0 Stairs Assumed single story 7.0 Elevator Assumed single story 8.0 Emergency Generator 0 - Exterior  Sub-Total 219 580  10% Circulation Factor - 58 area % req'd for corridors & access Net Sq. Ft.  Sub-total Net Building Area 5,472 11,793  15% Grossing Factor - 1,769 Walls, mechanical chases, etc. allowance  TOTAL GROSS BUILDING AREA REQUIRED 6,175 13,562 Gross Sq. Ft.  EXTERIOR SPACE NEED REQUIREMENTS  Parking, TOTAL  Public Parking 2 4  Staff Parking 12 14 7, double at shift change  Outdoor Patio Small area for grill and seating.			105	150	RTUs with control's system HW heater hoiler numps etc
2.0 Electrical Service 114 140 switchgear needs  3.0 I.T. Room inc in elect 90 space for additional (1) rack 4.0 Water Service/Sprinkler inc in mech 80 incoming water service, fire suppression piping, etc. 5.0 General Building Storage 120 6.0 Stairs Assumed single story 7.0 Elevator Assumed single story 8.0 Emergency Generator 0 - Exterior  Sub-Total 219 580  10% Circulation Factor - 58 area % req'd for corridors & access  SUPPORT/STORAGE TOTAL 219 638 Net Sq. Ft.  Sub-total Net Building Area 5,472 11,793 15% Grossing Factor - 1,769 Walls, mechanical chases, etc. allowance  TOTAL GROSS BUILDING AREA REQUIRED 6,175 13,562 Gross Sq. Ft.  EXTERIOR SPACE NEED REQUIREMENTS Parking, TOTAL Public Parking 2 4 Staff Parking 12 14 7, double at shift change  Outdoor Patio Small area for grill and seating.					
Comparison of the comparison	2.0	Electrical Service	114	140	
3.0   I.T. Room   inc in elect   90   space for additional (1) rack					(1) rack - cameras, remote access, alerting, phones, etc.,
5.0 General Building Storage 6.0 Stairs 7.0 Elevator 7.0 Elevator 8.0 Emergency Generator  Sub-Total 219 580  10% Circulation Factor 5UPPORT/STORAGE TOTAL 219 638 Net Sq. Ft.  Sub-total Net Building Area 15% Grossing Factor  TOTAL GROSS BUILDING AREA REQUIRED EXTERIOR SPACE NEED REQUIREMENTS Parking, TOTAL Public Parking 2 4 Staff Parking 2 4 Staff Parking 1 2 14 7, double at shift change Outdoor Patio  Stassumed single story - Assumed single story - Assumed single story - Assumed single story - Exterior  Assumed single story - Assumed single story - Exterior  Assumed single story - Exterior  Assumed single story - Assumed single story - Assumed single story - Exterior  Assumed single story - Assumed single story - Assumed single story - Exterior  Assumed single story - Exterior - Assumed single story - Exterior - Assumed single story - A	3.0	I.T. Room	inc in elect	90	
6.0 Stairs Assumed single story  7.0 Elevator Assumed single story  8.0 Emergency Generator 0 - Exterior  Sub-Total 219 580  10% Circulation Factor - 58 area % req'd for corridors & access  SUPPORT/STORAGE TOTAL 219 638 Net Sq. Ft.  Sub-total Net Building Area 5,472 11,793  15% Grossing Factor - 1,769 Walls, mechanical chases, etc. allowance  TOTAL GROSS BUILDING AREA REQUIRED 6,175 13,562 Gross Sq. Ft.  EXTERIOR SPACE NEED REQUIREMENTS  Parking, TOTAL  Public Parking 2 4  Staff Parking 12 14 7, double at shift change  Outdoor Patio Small area for grill and seating.	4.0	Water Service/Sprinkler	inc in mech	80	incoming water service, fire suppression piping, etc.
7.0 Elevator Assumed single story  8.0 Emergency Generator 0 - Exterior  Sub-Total 219 580  10% Circulation Factor - 58 area % req'd for corridors & access SUPPORT/STORAGE TOTAL 219 638 Net Sq. Ft.  Sub-total Net Building Area 5,472 11,793  15% Grossing Factor - 1,769 Walls, mechanical chases, etc. allowance  TOTAL GROSS BUILDING AREA REQUIRED 6,175 13,562 Gross Sq. Ft.  EXTERIOR SPACE NEED REQUIREMENTS  Parking, TOTAL Public Parking 2 4 Staff Parking 12 14 7, double at shift change  Outdoor Patio Small area for grill and seating.	5.0	General Building Storage		120	
Sub-Total   219   580	6.0	Stairs	-	-	Assumed single story
Sub-Total   219   580     10% Circulation Factor   -   58     area % req'd for corridors & access   SUPPORT/STORAGE TOTAL   219   638   Net Sq. Ft.   Net Sq. Ft.	7.0	Elevator	-	-	Assumed single story
10% Circulation Factor   58   area % req'd for corridors & access	8.0	Emergency Generator	0	-	Exterior
SUPPORT/STORAGE TOTAL  Sub-total Net Building Area  15% Grossing Factor  1,769  Walls, mechanical chases, etc. allowance  TOTAL GROSS BUILDING AREA REQUIRED  EXTERIOR SPACE NEED REQUIREMENTS  Parking, TOTAL  Public Parking  2 4  Staff Parking  12 14 7, double at shift change  Outdoor Patio		Sub-Total	219	580	
Sub-total Net Building Area 5,472 11,793  15% Grossing Factor - 1,769 Walls, mechanical chases, etc. allowance  TOTAL GROSS BUILDING AREA REQUIRED 6,175 13,562 Gross Sq. Ft.  EXTERIOR SPACE NEED REQUIREMENTS  Parking, TOTAL  Public Parking 2 4  Staff Parking 12 14 7, double at shift change  Outdoor Patio Small area for grill and seating.		-	-	58	area % req'd for corridors & access
15% Grossing Factor - 1,769 Walls, mechanical chases, etc. allowance  TOTAL GROSS BUILDING AREA REQUIRED 6,175 13,562 Gross Sq. Ft.  EXTERIOR SPACE NEED REQUIREMENTS  Parking, TOTAL  Public Parking 2 4  Staff Parking 12 14 7, double at shift change  Outdoor Patio Small area for grill and seating.		SUPPORT/STORAGE TOTAL	219	638	Net Sq. Ft.
15% Grossing Factor - 1,769 Walls, mechanical chases, etc. allowance  TOTAL GROSS BUILDING AREA REQUIRED 6,175 13,562 Gross Sq. Ft.  EXTERIOR SPACE NEED REQUIREMENTS  Parking, TOTAL  Public Parking 2 4  Staff Parking 12 14 7, double at shift change  Outdoor Patio Small area for grill and seating.		Sub-total Net Building Area	5 472	11 702	
TOTAL GROSS BUILDING AREA REQUIRED  6,175  13,562  Gross Sq. Ft.  EXTERIOR SPACE NEED REQUIREMENTS  Parking, TOTAL  Public Parking  2 4 Staff Parking  12 14 7, double at shift change  Outdoor Patio  Small area for grill and seating.					Walls, mechanical chases, etc. allowance
Parking, TOTAL Public Parking 2 4 Staff Parking 12 14 7, double at shift change  Outdoor Patio  Small area for grill and seating.	TOTA	8		,	
Parking, TOTAL Public Parking 2 4 Staff Parking 12 14 7, double at shift change  Outdoor Patio  Small area for grill and seating.				-,-,-	
Public Parking 2 4 Staff Parking 12 14 7, double at shift change  Outdoor Patio Small area for grill and seating.		•			
Staff Parking 12 14 7, double at shift change  Outdoor Patio Small area for grill and seating.		C,	2	4	
Outdoor Patio Small area for grill and seating.		S .		14	7, double at shift change
· · · · · · · · · · · · · · · · · · ·		-			- -
Dumpster Enclosure		Outdoor Patio			Small area for grill and seating.
		Dumpster Enclosure			





## **Village of Hoffman Estates**

Fire Station No. 21, 22, & Administration

Fire Station No. 22

## **FGMA**RCHITECTS

A. Public		,			
A. Public		Constantian / Page	Existing Area	Proposed Area	Notes (Comments
1.0   Entry Vestibule   50   70   150		Space Description/Room	(Sq. Ft.)	(Sq. Ft.)	Notes/Comments
2.0   Lobby/ Department Tradition   -   150     3.0   Training Room   698   1,000   Sized for 30 people (tables and chairs)   4.0   Training Storage   70   150   tables, chairs, props, etc.   5.0   Training Kitchenette   -   25   alcove at rear of training room   (1) mothers, PTSD manage, stress manage, diabetes manage, etc. Per It law, mothers room to be provided, and wellness room recommended per NFPA   (1) WC, (1) law each - constructed as storm shelters. (2) toilet rooms existing.   15% Circulation Factor   259   2,064   Net Sq. Ft.   (1) WC, (1) law each - constructed as storm shelters. (2) toilet rooms existing.   15% Circulation Factor   269   Net Sq. Ft.   (2) Workstations, (2) guest chairs, (6) closets   20   Mother Sq. Ft.   (2) Workstations, (2) guest chairs, (6) closets   275   (2) Workstations, (3) printers, laid out to have central conference table for training.   275   275   (2) Workstations, (3) printers, laid out to have central conference table for training.   275   2	A. Publi	с			
3.0   Training Room   6.98   1,000   Sized for 30 people (tables and chairs)	1.0	Entry Vestibule	50	70	
A	2.0	Lobby/ Department Tradition	-	150	
1.0	3.0	Training Room	698	1,000	Sized for 30 people (tables and chairs)
(1) mothers, PTSD manage, stress manage, diabetes manage, etc. Per It. law, mothers room to be provided, and wellness room recommended per NFPA	4.0	Training Storage	70	150	tables, chairs, props, etc.
Firefighter Resiliency/ Mothers Room   -   80   manage, etc. Per IL law, mothers room to be provided, and wellness room recommended per NFPA   1,00   1,795   15% Circulation Factor   269   2,064	5.0	Training Kitchenette	-	25	alcove at rear of training room
6.0 Firefighter Resiliency/ Mothers Room - 80 and wellness room recommended per NFPA  7.0 Single User Restroom - 4  Sub-Total 870 1,795  15% Circulation Factor 269 PUBLIC TOTAL 870 2,064  8. Administration  1.0 BC Office 0 See BC Suite in C 2.0 Officer Office see Officer Suite in C 2.0 Small Conference Room 474 inc in ff room  4.0 Firefighter Office 150 Total - 975  25% Circulation Factor - 244 ADMINISTRATION TOTAL - 1,219  C. Residential  1.0 Dayroom - 14  817 1,000 Greatroom concept  (3) fridges, (1) comm stove, (1) deep sink, (1) ADA sink, (1) microwave, (1) high end dishwasher (miele), ice/fill (2) Mirroom 150 Mirro					(1) mothers, PTSD manage, stress manage, diabetes
Single User Restroom - 4   52   320   10 WC, (1) lav each - constructed as storm shelters. (2) tollet rooms existing.    Sub-Total   870   1,795   15% Circulation Factor   269   Net Sq. Ft.					manage, etc. Per IL law, mothers room to be provided,
Total   Single User Restroom - 4   Sub-Total   870   1,795	6.0	Firefighter Resiliency/ Mothers Room	-	80	and wellness room recommended per NFPA
Sub-Total   870   1,795   269   269   269   200   20					
15% Circulation Factor   269   2,064   Net Sq. Ft.	7.0				toilet rooms existing.
PUBLIC TOTAL   870   2,064   Net Sq. Ft.			870		
B. Administration  1.0 BC Office 2.0 Officer Office see Officer Suite in C 2.0 Officer Office see Officer Suite in C 3.0 Small Conference Room  4.0 Firefighter Office  Sub-Total  Sub-Total  25% Circulation Factor ADMINISTRATION TOTAL  C. Residential  1.0 Dayroom - 14  817  1,000 Greatroom concept  (3) fridges, (1) comm stove, (1) deep sink, (1) ADA sink, (1) microwave, (1) high end dishwasher (miele), ice/fill stokes of the common supply closet  2.0 Kitchen - 14  3.0 Dining Room - 14  4.0 Kitchen Pantry  6.3 100  (3) shift pantry closet, (1) common supply closet  90 SF - bed, desk, (3) small lockers for bedding, door, walls to ceiling.  7.0 Womens Toilet/ Shower Room 265  7.0 Womens Toilet/ Shower Room 265  8.0 Single User Restrooms  1 See BC Suite in C 275  (2) workstations, (2) guest chairs, (6) closets  1 (2) workstations, (2) guest chairs, (6) closets  1 (2) workstations, (2) guest chairs, (6) closets  1 (3) gridget to bays. (7) workstations, (3) printers, laid out to have central conference table for training.  4 area % req'd for corridors & access  Net Sq. Ft.  (3) fridges, (1) comm stove, (1) deep sink, (1) ADA sink, (1) microwave, (1) high end dishwasher (miele), ice/fill stokers, (2) microwave, (1) high end dishwasher (miele), ice/fill stokes, (3) shift pantry closet, (1) common supply closet  90 SF - bed, desk, (3) small lockers for bedding, door, walls to ceiling.  7.0 Womens Toilet/ Shower Room 155 - 7.0 Womens Toilet/ Shower Room 265 - 8.0 Single User Restrooms - 600 Provide (6) rooms, with (1) WC, (1) sink and (1) shower					·
1.0 BC Office 2.0 Officer Office see Officer Suite in C 2.0 Officer Office see Officer Suite in C 3.0 Small Conference Room 474 inc in ff room 4.0 Firefighter Office  Sub-Total 25% Circulation Factor ADMINISTRATION TOTAL 4.1 Dayroom - 14 4.2 Dayroom - 14 4.3 Dining Room - 14 4.0 Kitchen - 14 4.0 Kitchen Pantry 4.0 Kitchen Pantry 5.0 Bunkrooms - 13 6.0 Mens Toilet/ Shower Room 5.0 Single User Restrooms 5.0 Single User Restrooms 5.0 Single User Restrooms 5.0 Single User Restrooms 5.0 Small Conference Room 474 inc in dayroom 475 inc in fr room 476 adjacent to bays. (7) workstations, (3) printers, laid out to have central conference table for training. 479 adjacent to bays. (7) workstations, (3) printers, laid out to have central conference table for training. 470 adjacent to bays. (7) workstations, (3) printers, laid out to have central conference table for training. 470 adjacent to bays. (7) workstations, (3) printers, laid out to have central conference table for training. 470 adjacent to bays. (7) workstations, (3) printers, laid out to have central conference table for training. 470 adjacent to bays. (7) workstations, (3) printers, laid out to have central conference table for training. 470 area % req'd for corridors & access 471 Net Sq. Ft.  472 area % req'd for corridors & access 473 net Sq. Ft.  474 area % req'd for corridors & access 475 Net Sq. Ft.  475 (3) fridges, (1) comm stove, (1) deep sink, (1) ADA sink, (1) microwave, (1) high end dishwasher (miele), ice/fill station, coffeem possible pot rack 470 area % req'd for corridors & access 474 area % req'd for corridors & access 475 Add for corridors & access 476 area % req'd for corridors & access 477 area % req'd for corridors & access 478 area % req'd for corridors & access 479 area % req'd for corridors & access 470 for corridors & access		PUBLIC TOTAL	870	2,064	Net Sq. Ft.
1.0 BC Office 2.0 Officer Office see Officer Suite in C 2.0 Officer Office see Officer Suite in C 3.0 Small Conference Room 474 inc in ff room 4.0 Firefighter Office  Sub-Total 25% Circulation Factor ADMINISTRATION TOTAL 4.1 Dayroom - 14 4.2 Dayroom - 14 4.3 Dining Room - 14 4.0 Kitchen - 14 4.0 Kitchen Pantry 4.0 Kitchen Pantry 5.0 Bunkrooms - 13 6.0 Mens Toilet/ Shower Room 5.0 Single User Restrooms 5.0 Single User Restrooms 5.0 Single User Restrooms 5.0 Single User Restrooms 5.0 Small Conference Room 474 inc in dayroom 475 inc in fr room 476 adjacent to bays. (7) workstations, (3) printers, laid out to have central conference table for training. 479 adjacent to bays. (7) workstations, (3) printers, laid out to have central conference table for training. 470 adjacent to bays. (7) workstations, (3) printers, laid out to have central conference table for training. 470 adjacent to bays. (7) workstations, (3) printers, laid out to have central conference table for training. 470 adjacent to bays. (7) workstations, (3) printers, laid out to have central conference table for training. 470 adjacent to bays. (7) workstations, (3) printers, laid out to have central conference table for training. 470 area % req'd for corridors & access 471 Net Sq. Ft.  472 area % req'd for corridors & access 473 net Sq. Ft.  474 area % req'd for corridors & access 475 Net Sq. Ft.  475 (3) fridges, (1) comm stove, (1) deep sink, (1) ADA sink, (1) microwave, (1) high end dishwasher (miele), ice/fill station, coffeem possible pot rack 470 area % req'd for corridors & access 474 area % req'd for corridors & access 475 Add for corridors & access 476 area % req'd for corridors & access 477 area % req'd for corridors & access 478 area % req'd for corridors & access 479 area % req'd for corridors & access 470 for corridors & access					
2.0 Officer Office see Officer Suite in C 3.0 Small Conference Room  4.0 Firefighter Office  Sub-Total  Sub-Total  - 975  25% Circulation Factor ADMINISTRATION TOTAL  - 1,219  C. Residential  1.0 Dayroom - 14  Sinc in dayroom A,0 Dining Room - 14  Sinc in from Hira Room A of Command Room A,0 Dining Room - 14  Sinc in from Hira Room A of Command Room A,0 Dining Room - 14  Sinc in from Hira Room A of Command Room A of Command Room A,0 Dining Room - 14  Sinc in from Hira Room A of Command Roo					
3.0 Small Conference Room 474 inc in ff room  4.0 Firefighter Office 150 700 adjacent to bays. (7) workstations, (3) printers, laid out to have central conference table for training.  Sub-Total - 975 25% Circulation Factor - 244 ADMINISTRATION TOTAL - 1,219 area % req'd for corridors & access Net Sq. Ft.  C. Residential  1.0 Dayroom - 14 817 1,000 Greatroom concept (3) fridges, (1) comm stove, (1) deep sink, (1) ADA sink, (1) microwave, (1) high end dishwasher (miele), ice/fill station, coffeem possible pot rack 3.0 Dining Room - 14 inc in dayroom 400 4.0 Kitchen Pantry 63 100 (3) shift pantry closet, (1) common supply closet 5.0 Bunkrooms - 13 730 1,170 walls to ceiling. 6.0 Mens Toilet/ Shower Room 155 - 7.0 Womens Toilet/ Shower Room 265 - 8.0 Single User Restrooms - 600 Provide (6) rooms, with (1) WC, (1) sink and (1) shower					
4.0 Firefighter Office  Sub-Total Su					(2) workstations, (2) guest chairs, (6) closets
Sub-Total   -     975     25% Circulation Factor   -   244	3.0	Small Conference Room	474	inc in ff room	
Sub-Total   -   975   25% Circulation Factor   -   244   area % req'd for corridors & access   Net Sq. Ft.		E: 0:1: 000	150	700	
25% Circulation Factor   244   area % req'd for corridors & access   Net Sq. Ft.	4.0		150		to have central conference table for training.
C. Residential   1.0   Dayroom - 14   817   1,000   Greatroom concept   (3) fridges, (1) comm stove, (1) deep sink, (1) ADA sink, (1) microwave, (1) high end dishwasher (miele), ice/fill station, coffeem possible pot rack   3.0   Dining Room - 14   inc in dayroom   450   station, coffeem possible pot rack   3.0   Kitchen Pantry   63   100   (3) shift pantry closet, (1) common supply closet   90 SF - bed, desk, (3) small lockers for bedding, door, sulface of the station of the sta			-		
C. Residential  1.0 Dayroom - 14  817  1,000 Greatroom concept  (3) fridges, (1) comm stove, (1) deep sink, (1) ADA sink, (1) microwave, (1) high end dishwasher (miele), ice/fill station, coffeem possible pot rack  3.0 Dining Room - 14  inc in dayroom  400  Kitchen Pantry  63  100  (3) shift pantry closet, (1) common supply closet  90 SF - bed, desk, (3) small lockers for bedding, door, walls to ceiling.  6.0 Mens Toilet/ Shower Room  155  7.0 Womens Toilet/ Shower Room  265  -  8.0 Single User Restrooms  - 600 Provide (6) rooms, with (1) WC, (1) sink and (1) shower					•
1.0 Dayroom - 14  817  1,000 Greatroom concept  (3) fridges, (1) comm stove, (1) deep sink, (1) ADA sink, (1) microwave, (1) high end dishwasher (miele), ice/fill station, coffeem possible pot rack  3.0 Dining Room - 14  inc in dayroom  400  Kitchen Pantry  63  100  (3) shift pantry closet, (1) common supply closet  90 SF - bed, desk, (3) small lockers for bedding, door, walls to ceiling.  6.0 Mens Toilet/ Shower Room  155  7.0 Womens Toilet/ Shower Room  265  Single User Restrooms  - 600  Provide (6) rooms, with (1) WC, (1) sink and (1) shower		ADMINISTRATION TOTAL	-	1,219	Net Sq. Ft.
1.0 Dayroom - 14  817  1,000 Greatroom concept  (3) fridges, (1) comm stove, (1) deep sink, (1) ADA sink, (1) microwave, (1) high end dishwasher (miele), ice/fill station, coffeem possible pot rack  3.0 Dining Room - 14  inc in dayroom  400  Kitchen Pantry  63  100  (3) shift pantry closet, (1) common supply closet  90 SF - bed, desk, (3) small lockers for bedding, door, walls to ceiling.  6.0 Mens Toilet/ Shower Room  155  7.0 Womens Toilet/ Shower Room  265  Single User Restrooms  - 600  Provide (6) rooms, with (1) WC, (1) sink and (1) shower	C Desid	lauration!			
(3) fridges, (1) comm stove, (1) deep sink, (1) ADA sink, (1) microwave, (1) high end dishwasher (miele), ice/fill station, coffeem possible pot rack  3.0 Dining Room - 14 inc in dayroom 400  4.0 Kitchen Pantry 63 100 (3) shift pantry closet, (1) common supply closet  90 SF - bed, desk, (3) small lockers for bedding, door, walls to ceiling.  6.0 Mens Toilet/ Shower Room 155 -  7.0 Womens Toilet/ Shower Room 265 -  8.0 Single User Restrooms - 600 Provide (6) rooms, with (1) WC, (1) sink and (1) shower			817	1 000	Greatroom concept
2.0 Kitchen - 14 inc in dayroom 450 station, coffeem possible pot rack 3.0 Dining Room - 14 inc in dayroom 400 4.0 Kitchen Pantry 63 100 (3) shift pantry closet, (1) common supply closet 90 SF - bed, desk, (3) small lockers for bedding, door, walls to ceiling. 6.0 Mens Toilet/ Shower Room 155 - 7.0 Womens Toilet/ Shower Room 265 - 8.0 Single User Restrooms - 600 Provide (6) rooms, with (1) WC, (1) sink and (1) shower	1.0	Dayroom - 14	017	1,000	
2.0Kitchen - 14inc in dayroom450station, coffeem possible pot rack3.0Dining Room - 14inc in dayroom4004.0Kitchen Pantry63100(3) shift pantry closet, (1) common supply closet5.0Bunkrooms - 137301,170walls to ceiling.6.0Mens Toilet/ Shower Room155-7.0Womens Toilet/ Shower Room265-8.0Single User Restrooms-600Provide (6) rooms, with (1) WC, (1) sink and (1) shower					
3.0 Dining Room - 14 inc in dayroom 400 4.0 Kitchen Pantry 63 100 (3) shift pantry closet, (1) common supply closet 90 SF - bed, desk, (3) small lockers for bedding, door, walls to ceiling. 6.0 Mens Toilet/ Shower Room 155 - 7.0 Womens Toilet/ Shower Room 265 - 8.0 Single User Restrooms - 600 Provide (6) rooms, with (1) WC, (1) sink and (1) shower	2.0	Kitchen - 14	inc in dayroom	450	
4.0 Kitchen Pantry  63 100 (3) shift pantry closet, (1) common supply closet  90 SF - bed, desk, (3) small lockers for bedding, door, walls to ceiling.  6.0 Mens Toilet/ Shower Room  7.0 Womens Toilet/ Shower Room  8.0 Single User Restrooms  100 (3) shift pantry closet, (1) common supply closet  90 SF - bed, desk, (3) small lockers for bedding, door, walls to ceiling.  - 600 Provide (6) rooms, with (1) WC, (1) sink and (1) shower					
5.0 Bunkrooms - 13 730 1,170 walls to ceiling.  6.0 Mens Toilet/ Shower Room 155 -  7.0 Womens Toilet/ Shower Room 265 -  8.0 Single User Restrooms - 600 Provide (6) rooms, with (1) WC, (1) sink and (1) shower	***************************************				(3) shift pantry closet. (1) common supply closet
5.0         Bunkrooms - 13         730         1,170         walls to ceiling.           6.0         Mens Toilet/ Shower Room         155         -           7.0         Womens Toilet/ Shower Room         265         -           8.0         Single User Restrooms         -         600         Provide (6) rooms, with (1) WC, (1) sink and (1) shower		, , , , , , , , , , , , , , , , , , , ,	33		
6.0         Mens Toilet/ Shower Room         155         -           7.0         Womens Toilet/ Shower Room         265         -           8.0         Single User Restrooms         -         600         Provide (6) rooms, with (1) WC, (1) sink and (1) shower	5.0	Bunkrooms - 13	730	1.170	
7.0 Womens Toilet/ Shower Room 265 - 8.0 Single User Restrooms - 600 Provide (6) rooms, with (1) WC, (1) sink and (1) shower	V0000000000000000000000000000000000000			-	
8.0 Single User Restrooms - 600 Provide (6) rooms, with (1) WC, (1) sink and (1) shower				-	
	200200000000000000000000000000000000000		-	600	Provide (6) rooms, with (1) WC, (1) sink and (1) shower
	***************************************				(45) lockers, (4) sinks

14.0 PubEd Storage

16.0 HazMat Storage

18.0 | Seasonal Storage

15.0 EMS Supply

17.0 Bay Storage

#### **SECTION 4.2**





## **Village of Hoffman Estates**

Fire Station No. 21, 22, & Administration

Fire Station No. 22

### **FGMARCHITECTS**

public education supplies

salt, oil dry, and foam storage

area % reg'd for corridors & access

general equipment storage

Net Sq. Ft.

centralized EMS supply for department

snowblower, salt, weedwacker, shovels, etc.

120

200

100

100

64

500

10,009

10,509

updated 11/18/2022 FGM # 22-3489.01

Constant				FGM # 22-3489.01
	Space Description/Room	Existing Area (Sq. Ft.)	Proposed Area (Sq. Ft.)	Notes/Comments
				free weights, cardio equipment, stretching area,
10.0	Fitness Room	609	800	resistence training
11.0	Janitor Closet/Supplies		45	
12.0	Residential Laundry		150	(2) pairs of washers & dryers, supplies, storage
13.0	BC Bunk Suite		375	Office w/ (1) desk, (2) guest chairs & (3) closets Bunk room with (3) lockers & (3) bedding lockers Toilet room w/ (1) WC, (1) sink, (1) shower.
14.0	Officer Suite	466	-	officer bunk included with main bunk rooms
	Sub-Total	3,105	6,090	
	20% Circulation Factor	-	1,218	area % req'd for corridors & access
	RESIDENTIAL TOTAL	3,105	7,308	Net Sq. Ft.
D. Appa	ratus Area			(2) 20'W x 85'L & (2) middle 17'W x 85'L - drive thru
				bays
1.0	Apparatus Bays - (4) Bays	3,726	6,290	engine, squad, tower, medic, reserve truck, reserve
2.0	Small Vehicle Bays	-	900	(2) 15'W x 30'L - back in bays, BC buggy
3.0	Turnout Gear Lockers	on bay floor	920	(45) sets of open rack lockers & open shelves for 2nd set of gear, negative pressure
4.0	Bay Laundry	260	180	(1) Large Extractor, washer/dryer, slop sink, drying closet/cabinet, etc. Look at possibility of installing a lift on bay floor to raise hose for drying.
5.0	Decon/EMS Dirty	inc in bay laundry	120	(1) st.stl scullery sink with sideboards, st.stl. decon shower, boot wash
6.0	EMS Supply	-	25	small closet for supplies
7.0	SCBA	156	180	SCBA compressor/fill station & oxygen tanks. Sink & counter for mask/backpack testing.
8.0	Work Room/ Tools/ Equipment	126	200	toolbox, work bench, spare parts storage, air compressor
9.0	Toilet	22	80	(1) WC, (1) lav, (1) shower
10.0	Hose Storage	inc in bay laundry	20	alcove off of bay floor
11.0	Chargers/Mail Alcove	72	90	located on corridor/ramp from house to bays.
12.0	Quartermaster Storage		100	gloves, helmets, hoods, uniforms, batteries, etc.
13.0	Central Supply Storage	currently at 24	320	centralized supplies for department

currently at 24

currently at 24

currently at 24

inc in workroom

Sub-Total

5% Circulation Factor

**APPARATUS AREA TOTAL** 

26

4,388

4,388

## **FGMA**RCHITECTS

#### **VILLAGE OF HOFFMAN ESTATES**

Fire Station No. 21 & No. 22 Study

### **SECTION 4.2**





**Dumpster Enclosure** 

## **Village of Hoffman Estates**

Fire Station No. 21, 22, & Administration

Fire Station No. 22

## **FGMA**RCHITECTS

	Space Description/Room	Existing Area (Sq. Ft.)	Proposed Area (Sq. Ft.)	Notes/Comments
. Supp	oort/Storage			
1.0	Mechanical Room	230	350	RTUs with control s system, HW heater, boiler, pumps, etc
				MDP, ATS, panels, room for future charging power
2.0	Electrical Service	114	175	switchgear needs
				(1) rack - cameras, remote access, alerting, phones, etc.,
3.0	I.T. Room	inc in elect	90	space for additional (1) rack
4.0	Water Service/Sprinkler	inc in mech	80	incoming water service, fire suppression piping, etc.
5.0	General Building Storage		120	
6.0	Stairs	378	-	Assumed single story
7.0	Elevator	-	-	Assumed single story
8.0	Emergency Generator	82	-	Exterior
	Sub-Total	804	815	
	10% Circulation Factor	-	82	area % req'd for corridors & access
	SUPPORT/STORAGE TOTAL	804	897	Net Sq. Ft.
-	Sub-total Net Building Area	9,167	21,997	
	15% Grossing Factor	-	3,300	Walls, mechanical chases, etc. allowance
TOT	AL GROSS BUILDING AREA REQUIRED	11,580	25,296	Gross Sq. Ft.
EXTE	RIOR SPACE NEED REQUIREMENTS	_		
	Parking, TOTAL			
	Public Parking	11	4	
	Staff Parking	14	28	14, double at shift change
	Outdoor Patio			Small area for grill and seating.





## **Village of Hoffman Estates**

Fire Station No. 21, 22, & Administration

#### **Fire Administration**

## **FGMA**RCHITECTS

	Space Description/Room	Existing Area (Sq. Ft.)	Proposed Area (Sq. Ft.)	Notes/Comments
A Dubli				
A. Publi	Entry Vestibule	0	70	
1.0	Entry vestibule	Ü	70	small fire dept history, waiting chairs, small 4-6 person
2.0	Lobby/ Department Tradition	152	300	table for fire prevention meetings
3.0	Training Room	-	-	currently using VH training.
	Sub-Total	152	370	, , ,
	15% Circulation Factor		56	area % req'd for corridors & access
	PUBLIC TOTAL	152	426	Net Sq. Ft.
		,	·	
	nistration	100	100	
1.0	Fire Chief Office	180	180	(1) desk, (2) guest chairs
2.0	Closet	0	20	
3.0	Deputy Chief Office	161	180	(1) desk, (2) guest chairs
4.0	Closet	0	20	
5.0	Deputy Chief Office	145	180	(1) desk, (2) guest chairs
6.0	Closet	0	20	
7.0	BC Office	145	180	(1) desk, (2) guest chairs, covers roles of training and safety
8.0	Closets	0	60	(3) closets
9.0	Administrative Assistant Office	70	150	currently a workstation cubicle. Proposed is a separate
10.0		70 70	64	office. (1) desk, (2) guest chairs.
11.0	Administrative Analyst Hotelling Offices	130	128	open cubicle 8'x8' workstation
12.0	Fire Protection - Chief Inspector Office	355	200	(2) open cubicle 8'x8' workstations
13.0	Fire Inspectors	inc in above	256	(1) desk, (2) guest chairs, lay-out plan table/ monitor area
13.0	File hispectors	IIIC III above	230	(4) open deep-counter cubicle 8'x8' workstations
14.0	File/ Plan Storage	338	225	current plan storage, long term record storage, lay-out table/ monitor area for reviews
15.0	Future Office - EMS Officer?	-	180	(1) desk, (2) guest chairs
16.0	Closet	_	20	(1) uesk, (2) guest citalis
17.0	Conference Room	317	300	12-14 people
18.0	Break Room	119	225	fridge, sink, microwave, casework storage, table for 4-6 people
19.0		c in archive storage	80	copier/printer, supply storage, casework storage, lay-out space
20.0	File Room/ Area	80	120	access off corridors, or adjacent to administrative assistant
21.0	Quartermaster Storage	120	100	department gear supply storage
22.0		65	80	knox boxes, alarms, etc.
23.0		500	350	requires purging of files and department stuff.
24.0	Janitor's Closet	inc in VH space	50	mop sink, supply storage, etc.
25.0	Single User Restrooms	131	160	(2) single user rooms, each w/ (1) WC, (1) lav, & (1) shower
				uniform and toiletry storage for Administration, either
26.0	Locker Room area	_	160	adjacent or connected to the toilet rooms - (8) lockers
				located near rear entry, open rack lockers to store
27.0	Turnout Gear	-	100	administration's gear - (5) lockers
				located near rear entry, open rack lockers to store fire
28.0	Fire Prevention Gear Storage	-	100	prevention's gear - (5) lockers
	Sub-Total	2,926	3,888	· · · · · · · · · · · · · · · · · · ·
	25% Circulation Factor	-	972	area % req'd for corridors & access
	ADMINISTRATION TOTAL	2,926	4,860	Net Sq. Ft.
		, ,	, I	•





## **Village of Hoffman Estates**

Fire Station No. 21, 22, & Administration

#### **Fire Administration**

## **FGMA**RCHITECTS

		Existing Area	Proposed Area	
	Space Description/Room	(Sq. Ft.)	(Sq. Ft.)	Notes/Comments
C. Resid	ential			
1.0	Not Applicable			
	Sub-Total	-	-	
	20% Circulation Factor		-	area % req'd for corridors & access
	RESIDENTIAL TOTAL	-	- 100	Net Sq. Ft.
D. Appa	ratus Area			
			refer to notes option	If possible, inside vehicle parking - (4) 15'W x 30'L - back
1.0	Small Vehicle Bays	-		in bays - if possible? About 1,800 s.f.
	Sub-Total		-	
	5% Circulation Factor		-	area % req'd for corridors & access
	APPARATUS AREA TOTAL	-	-	Net Sq. Ft.
<b>-</b> 6	/ 6			
E. Suppo	ort/Storage			
				Administration occupies. RTUs with control s system,
1.0	Mechanical Room	ing in VIII space		HW heater, boiler, pumps, etc Can be eliminated if
1.0	Mechanical Room	inc in vir space	refer to notes option	combined with main fire station.
				Administration occupies.
2.0	Electrical Service	inc in archive storage	refer to notes ontion	MDP, ATS, panels. Can be eliminated if combined with main fire station.
3.0	I.T. Room	inc in VH space	50	(1) rack - cameras, remote access, alerting, phones, etc.,
3.0	1.1. 1.0011	IIIe III VII space	30	Administration occupies.
4.0	Water Service/Sprinkler	inc in VH space	refer to notes option	Incoming water service, fire suppression piping, etc.
5.0	Department Storage	-	80	medining water service, me suppression piping, etc.
6.0	Stairs	inc in VH space	-	Assumed single story
7.0	Elevator	inc in VH space	-	Assumed single story
8.0	Emergency Generator	inc in VH space	-	Exterior
	Sub-Total	-	130	
	10% Circulation Factor	-	13	area % reg'd for corridors & access
	SUPPORT/STORAGE TOTAL	-	143	Net Sq. Ft.
	•		1 1	
	Sub-total Net Building Area	3,078	5,429	
	15% Grossing Factor	_	814	Walls, mechanical chases, etc. allowance
TOTA	L GROSS BUILDING AREA REQUIRED	3,990	6,243	Gross Sq. Ft.
EXTE	RIOR SPACE NEED REQUIREMENTS			
	Parking, TOTAL			
	Public Parking	?	3	
	Staff Parking	•	3	

## Fire Station No. 21 Existing Condition Report











#### Fire Station No. 21 - Existing Building Condition Report

Fire Station No. 21 was originally constructed in 1960. A fitness and locker room addition was constructed in the 1990's. The original building and addition were constructed of CMU masonry bearing walls clad with veneer brick. The existing membrane roof over the apparatus bays is pitched and supported by structural steel joists. The existing membrane roofs over the residence wings are flat and supported by structural steel joists. The interior walls at this station are primarily CMU block partitions in the apparatus bay, bay support and residence areas.

#### **Site and Parking**

- Visitation by the public proves difficult due to there being (3)
  entrance doors to approach with no clear main entrance noted.
  In addition, all but (1) entrance or egress exit is not accessible.
  These issues need to be addressed.
- Fourteen (14) public and staff parking spaces for the facility are
  provided on the Southwest side of the station. One (1) ADA
  parking space is provided at the main entry. There are not
  enough parking spaces provided in the parking lot and street
  parking is not allowed in this neighborhood to accommodate all
  staff vehicles on shift or during shift change when the required
  parking count doubles. Parking issues need to be addressed.
- The concrete apron, concrete patio, asphalt parking lot and asphalt drives are in poor condition and have areas of significant cracking and should be replaced in the near future. If not replaced, water will continue to penetrate below the paved surface to the base and degrade the surface.
- Asphalt in front of the trash enclosure appears to have been replaced recently but will need to be replaced again soon if not replaced with concrete to hold up to the weight of the garbage trucks being exerted on it weekly.
- Existing masonry trash enclosure gates appear to be in fair condition, but hardware is starting to fall apart and should be replaced in the near future. Steel bollards and framed gate doors should be provided in lieu of composite wood framing for longer life cycle and durability. Several areas of brick veneer were noted as having cracked grout joints at walls and limestone caps. These issues should be addressed by tuckpointing all of the exterior brick veneer walls and limestone caps or replacing limestone caps in kind or with aluminum coping.

## Fire Station No. 21 Existing Condition Report









#### **Building Envelope:**

- The existing pitched roof at apparatus bays and both residence wings' flat roofs consist of a single ply roofing membrane and rigid insulation that is supported by steel decking and bar joists. The roofing membrane appears to be in good condition after being replaced in 2011. It does not appear that additional insulation was added to the roofs when replaced. Existing roof insulation appears to be half of the required amount based on today's construction standards and Energy Code requirements. This condition results in a higher energy usage and cost for the Owner and needs to be addressed.
- Existing roof deck overhangs at the apparatus bays expose the steel roof deck outside the building, this condition does not meet today's construction standards and Energy Code requirements. Existing exterior wall and roof conditions allow for thermal transfer and potential moisture issues that affect the interior of the building and masonry cavity wall. This condition results in a higher energy usage cost to the owner and deterioration of the exposed steel deck by rust. This issue needs to be addressed.
- Existing soffits at the north side of both residence wings have the
  existing steel roof decks exposed to exterior unconditioned air
  due to the soffited areas having air transfer grilles. Existing
  transfer grilles do not appear to be original but have since been
  covered up with cardboard to stop unconditioned air from
  entering the building through the soffits. This condition does not
  meet today's construction standards and Energy Code
  requirements. This issue needs to be addressed.
- Existing soffits at entry doors do not have gutters or down spouts, this limits staff and visitors cover from rainfall when entering and exiting the building as well as not directing water away from doors so that puddles cannot form and potentially freeze in the winter months. This issue should be addressed.
- All existing aluminum coping has large gaps between the face of coping and exterior walls, this condition allows for insects and small animals to potentially infest and damage the existing exterior wall and roof membrane. This issue should be addressed.
- Cavity walls contain approximately 1" of rigid insulation. This is a third of the required amount based on today's construction standards and Energy Code requirements. This condition results in a higher energy usage and cost for the Owner.

## Fire Station No. 21 Existing Condition Report









#### **Building Envelope:**

- There are several steel lintels at window and door openings that have cracked mortar joints. If not addressed these lintels will continue to allow water to penetrate the cavity wall and potentially deteriorate the existing steel lintels. These issues should be addressed by tuckpointing all lintels with cracked or missing mortar joints.
- Several areas of brick veneer were noted having cracked grout
  joints at walls, parapets, and sills. Though some areas appear to
  have been tuck pointed or caulked, there were many other areas
  that have been yet to be addressed. These issues appear to be the
  result from water penetrating the cavity wall from multiple
  sources such as parapets, and heads and sills of windows. These
  issues should be addressed by tuckpointing all of the exterior brick
  veneer walls.
- Due to the time frame in which the building was constructed and from reviewing the original construction drawings, the exterior cavity walls contain 0" to less than 1" of rigid insulation. This is a quarter of the required amount based on today's construction standards and Energy Code requirements. This condition results in a higher energy usage and cost for the Owner. This issue needs to be addressed.
- The glazing at existing hollow metal window frames above front and rear apparatus bay doors have been removed and replaced with painted plywood. There is no insulated glazing units or wall cavity insulation at these openings in the exterior wall, this condition does not meet today's construction standards and Energy Code requirements. This condition results in a higher energy usage cost to the owner. It is suggested all window units and sealant be replaced with more energy efficient windows to reduce energy usage and cost for the Owner.
- Existing glazing units at the East and West sides of apparatus bay
  wood frames are original plate glass and do not meet today's
  construction standards and Energy Code requirements. This
  condition results in a higher energy usage cost to the owner. It is
  suggested all window units and sealant be replaced with more
  energy efficient windows to reduce energy usage and cost for the
  Owner.
- The existing aluminum clad wood windows appear to be in fair shape, some window leaks were reported. All existing window sealant has several gaps and is no longer pliable due to weathering and needs to be addressed. It is suggested all windows and sealant be replaced with more energy efficient units.

## Fire Station No. 21 Existing Condition Report













#### **Building Envelope:**

- The existing glass sectional overhead doors have missing glass cracked seals and do not meet the current energy code. This condition results in a higher energy usage and cost for the Owner. Overhead doors appear to be at the end of their life expectancies and should be replaced soon.
- All exterior grouted solid hollow metal frames and doors have started to rust through the weathered paint finish. It is suggested that all exterior hollow metal doors and frames be replaced with insulated doors and thermally broken frames to reduce energy usage and cost for the Owner.
- The infilled front and rear west residence wing openings are clad with painted wood paneling. The exterior wood paneling finishes are faded and deteriorating. This type of construction is subpar to typical commercial building construction. Due to the wall's construction type and the exterior cladding starting to show signs of deterioration it is suggested that they be replaced with a more suitable cladding material and insulation to reduce energy usage and cost for the Owner.

#### **Accessibility:**

Since the building was constructed and last renovated, accessibility requirements have changed with the Americans with Disabilities Act (ADA). The accessibility guidelines mandate that all public facilities are to be designed, constructed, or altered to assure equal accessibility to all members of society. If any type of renovation within the building occurs, multiple accessibility violations would need to be addressed. The violations range from minor issues to larger problems that would require significant renovation work. Below is a summary of violations reviewed during the building assessment:

- All entrances and egress exits for the facility do not meet ADA
  requirements due to not providing ramps at existing elevation
  changes at the gas curbs. Required push/pull door clearances and
  door hardware as required per code do not exist and do not allow
  a handicapped visitor or employee to enter, exit or traverse the
  facility safely.
- Interior room signage is not provided within the building. ADA compliant signage needs to be provided as required.

# SECTION 5.1 Fire Station No. 21 Existing Condition Report















#### Accessibility:

- Most doors that exit to and from occupiable rooms along the path
  of egress do not have the required push/pull clear floor space
  provided that allows a handicapped visitor or employee to enter
  or exit the facility safely.
- The majority of door hardware throughout the station is knobs.
   These would need to be replaced with ADA compliant lever handles that do not require tight grasping, pinching, or twisting of the wrist to operate.
- All toilet/shower rooms do not meet ADA requirements in regard to reach ranges, plumbing fixture clearances, turning radius clearances and push/pull door clearance requirements. Inside the toilet rooms there is not enough clear floor space for a person in a wheelchair to turn around, transfer onto the toilet or open the door to exit. Also, the plumbing fixtures and several toilet accessories are not ADA compliant and the required grab bars are not provided.
- All toilet/shower rooms are lacking ADA compliant shower stalls.
- All toilet/shower rooms are lacking ADA compliant toilet stalls.
- Sinks in toilet/shower rooms and kitchen do not allow front approach wheelchair access as required per ADA. Sink bases and counter tops would need to be replaced with ADA compliant sink bases.
- Kitchen Countertops do not meet ADA requirements in regard to maximum work surface height requirements. The countertop is too high for a person in a wheelchair to access.
- All kitchen and toilet room casework are not provided with ADA complaint door and drawer pulls. Replace pulls as required.

## **SECTION 5.1** Fire Station No.21 **Existing Condition Report**









#### **Building Code Issues:**

- Code required fire separations are not provided between the Storage (Apparatus Bay) and Residence (Bunks, Dayroom, Kitchen, etc) This issue needs to be addressed.
- Mechanical /Electric room is currently being used for overflow storage and the minimum clearances for panels and water service are not provided. Access to these areas allows for tampering with equipment. Best practice is to provide a location for this equipment that can be secured and reduce storage in this space.
- All exposed sink and lavatory piping not covered or protected.
- Commercial hood in kitchen not provided with required make-up air unit. This issue needs to be addressed if hood is altered in the future.
- All emergency egress doors do not have the required panic door hardware.

#### **NFPA Life Safety Code:**

The National Fire Prevention Association (NFPA) publishes a series of safety codes and standards devoted to minimizing the possibility of fire and other risks. As a public facility dedicated to minimizing fires and other risks, this Fire Station is required to follow the standards set forward by the NFPA Life Safety Code Standards. Below is a list of NFPA violations that were observed:

There is no NFPA 72 compliant gas detection system within the Apparatus Bay.

NFPA 1851 lays out the guidelines for handling elements that have been contaminated with hazardous materials. Many of the standards are related to standard operating procedures that need to be developed by the Fire Department. However, some of the procedures also require physical spaces that needs to be integrated into the existing building. Listed below are some of the observed violations of NFPA 1851 due to space limitations within the current facility:

To prevent cross contamination, a designated decontamination area is required for routine cleaning of personal protective equipment that has been in contact with hazardous materials. There is no dedicated decontamination room observed within the current facility, all fire gear is being stored on the Apparatus Bay floor.

## Fire Station No. 21 Existing Condition Report











#### **General Notes:**

- Most of the facility has 2'x2' acoustical ceiling tiles that appear to be in good condition. There were some stained and damaged tiles, those tiles should be replaced.
- All existing light fixtures throughout the facility were replaced with more efficient LED light fixtures a couple years ago.
- The countertops are plastic laminate with a composite wood core, this product type at a wet surface location is not suggested due to possible delamination of the finish and deterioration of the composite wood core. It is suggested that all countertops in toilet rooms and kitchen be replaced with a more durable product like solid surface or quartz.

#### **Mechanical Systems:**


#### **East Residence**

- The east side of the building is heated and cooled by (1) York model TG8S080, 2010 and (1) Carrier model 59SC2, 2013. Both furnaces are gas fired, standard efficiency, down flow and appear to be in good condition. Each furnace has an associated humidifier and cooling coil. The associated 3-ton condensing units are located on grade outside of the mechanical room. The Carrier condensing unit on the east side is past its useful life and should be replaced in the near future.
- Combustion air is provided by two door louvers, one high and one low. The supply ductwork is routed underground to floor registers.
   The return is routed above the ceiling, to ceiling grilles. The furnaces are controlled by programmable thermostats.
- The kitchen has a commercial exhaust hood with a fire suppression system. No make-up air for the hood was observed.
   The expected useful life of this equipment is 20 years.
- Several rusted or damaged floor supply registers were noted.
   Replace the floor supply registers that are damaged or in poor condition with new heavy-duty registers.

## Fire Station No. 21 Existing Condition Report













#### **West Residence**

- The west side of the building is heated and cooled by (1) Carrier furnace. Carrier model59SC2, 2019. The furnace is gas fired, standard efficiency, down flow. The furnace has an associated humidifier and cooling coil. The associated 2-ton condensing unit is located on grade outside of the mechanical room.
- This system serves the Bunk Room and offices. The supply ductwork is routed underground to floor registers. The return is routed above the ceiling to wall grilles. No means of combustion air was observed.
- Several rusted or damaged floor supply registers were noted.
   Replace the floor supply registers that are damaged or in poor condition with new heavy-duty registers.

#### **Plumbing Systems:**

#### Sanitary

• The underground sanitary waste and vent system utilizes hub and spigot cast iron and schedule 40 PVC. The above grade sanitary waste and vent system is generally hub and spigot cast iron (3" and larger) and galvanized pipe (2" and smaller). Exposed piping appears to be in fair condition. It is suggested to periodically inspect (camera) and clean (rodding acceptable, jetting preferred) the sanitary system to increase the life expectancy of the system.

#### **Exterior**

 The building's exterior has wall hydrants, overflow scuppers, and roof drain piping. The overflow scuppers splash into a gutter that ties directly into the storm system (schedule 40 PVC) underground on the west side of the building. On the east side the scuppers splash to grade using the gutter system. The roof drains splash on grade utilizing schedule 40 PVC. The storm system appears to be in fair to good condition.

## **SECTION 5.1** Fire Station No. 21

# **Existing Condition Report**













#### **Plumbing Systems:**

#### Interior

- The building has separate domestic and fire protection water services. The fire suppression service is ductile iron pipe while the domestic service is copper. The water piping is generally copper pipe with soldered joints and some sections of galvanized piping. The building has a 2" water meter, and a 2" RPZ for domestic water. 2" domestic water service and 4" fire protection. Exposed water piping is in good condition.
- Isolation valves were not observed at all fixtures. It is suggested that isolation valves be added. Without adding isolation valves, repairs will likely require all domestic water to be shut down.
- It is suggested that any galvanized piping be removed and replaced with copper piping when the opportunity presents itself.
- Existing water heater is in fair condition but is nearing the end of its useful life cycle and missing code required expansion tank. It is suggested that the hot water heater be replaced with more efficient unit with code required expansion tank.

# Fire Station No. 21 Existing Condition Report















#### **Electrical System:**

- The electrical service to the building is an overhead type rated at 200-amps, delta 120/240v, single phase system.
  - Per ComEd's record the peak demand occurred in January 2022 with 13.50 KW (56 amps). The electrical service has a spare capacity of 144 amps for little future expansion.
- The main electrical panel is in the mechanical room that is sub feeding one panel and then the sub feeding panel is sub feeding two panels, so there is total of (4) panels. The electrical panels are still working properly, but in poor condition since they are the ends of their lifespans and at their maximum capacities.
- It is suggested that incoming service be upgraded from 200A to 300A and changed from 120/240v1ph to 120/208v 3ph. This will help off load just being a single phase and would use less panels since two panels are at each side of the building. Each side should have one bigger panel with 42 circuit breakers instead of using two small panels with less circuit breakers.
- Existing sprinkler and domestic water piping runs over electric panels and IT racks. Pipes need to be rerouted away from the electrical panels in the mechanical room and some of the equipment needs to be rearranged, like the automatic transfer switch, for additional clearance and non-violation of the codes.
- Existing meter is on the exterior of the mechanical room and where the incoming service enters the building. The building is backed-up by a generator. Generator appears to be near its end of lifespan assuming it's more than 25 years old.

#### Fire Alarm System:

 Existing Notifier fire alarm panel is located in the mechanical/electrical room. Pull stations are provided as required. Existing system appears to be regularly serviced and in good working condition but is out of date and does not meet current code requirements. Existing fire alarm system and fire alarm devices to be replaced as required to meet current codes.

# SECTION 5.1 Fire Station No. 21 Existing Condition Report







#### Interior:

#### Lobby

- The lobby is undersized and main entry does not have a separate vestibule. Not having this separation of heating/cooling zones from the exterior results in higher energy usage. It is suggested that the existing hollow metal door and frame be replaced with a thermally broken frame and insulated door system and potentially a new vestibule be added.
- The existing main entry door does not have the International Building Code (IBC) required exiting hardware and the door is designated as a fire exit with signage but does not have panic/exit hardware. The code required emergency exit door hardware needs be provided at this location.
- Code required fire separations are not provided between apparatus bay and lobby. Existing CMU call construction and penetrations to be reviewed and existing hollow metal frames, glazing and doors to be rated.
- Elevation changes at gas curb between lobby and watch office does not allow a handicapped employee or visitor to enter or safely egress out of the station office as required by accessibility and building codes. This issue needs to be addressed.
- Flooring appears to be original to the building and is reaching the end of its lifespan. It is suggested that flooring be replaced.
- Painted CMU is reaching the end of its lifespan and needs to be repainted.

# SECTION 5.1 Fire Station No. 21 Existing Condition Report















#### Office

- Office is undersized. (1) workstation and file cabinets are provided but should be larger to meet the Department 's operational needs. Flooring appears to be original to the building and is reaching the end of its lifespan. It is suggested that flooring be replaced.
- Office has direct emergency access to the Apparatus Bays; the
  doors are not equipped with weather seals which could allow
  contaminants to penetrate the space. This issue needs to be
  addressed by providing weather seals at a minimum, but a better
  buffer zone should be provided to maintain isolation between
  'cold' and 'hot' zones.
- Elevation changes at gas curb between lobby and watch office do not allow a handicapped employee or visitor to enter or safely egress out of the station office as required by accessibility and building codes. This issue needs to be addressed.

#### Men's Toilet/Shower/Locker Room

- The Men's Toilet/Shower/Locker Room is accessed from the bunk room and apparatus bay and is undersized. The locker room consists of one (1) floor-mount, flush valve water closet, one (1) urinal, two (2) lavatories and one (1) shower. The water closet, urinals, lavatory faucets and shower appear to be in fair condition.
- The Men's Toilet/Shower/Locker Room is currently not meeting the Illinois Plumbing Code (IPC) by not having lavatories that utilize a thermostatic mixing valve to limit hot water temperature. The code required floor drain, piping and thermostatic mixing valves at the lavatory need to be provided. Also, it is suggested that all the lavatories' hardware be replaced because they are at the end of their life spans.
- The Men's Toilet/Shower/Locker Room is located directly off the apparatus bay and creates adjacency issues in which exhaust transfer from the vehicles in the apparatus bay can enter into the Toilet/Shower/Locker Room. The apparatus bays and residence wing are two separate closed mechanical systems/ zones but due to regular use of the locker room as a path for emergency calls and typical activities, exhaust from the vehicles is emitted into the Toilet/Shower/Locker Room every time the door opens and is then recirculated into the rest of the building. The lack of seals on the locker room door into the apparatus bays is also aiding in the transfer of exhaust. These issues need to be addressed.

# Fire Station No.21 Existing Condition Report















#### Men's Toilet/Shower/Locker Rooms

- Elevation changes at gas curb between Men's
   Toilet/Shower/Locker Rooms and apparatus bay does not allow a
   handicapped employee or visitor to enter or safely egress out of
   the space as required by accessibility and building codes. This
   issue needs to be addressed.
- The Men's Toilet/Shower/Locker Rooms do not meet ADA requirements in regard to reach ranges, plumbing fixture clearances, turning radius clearances and push/pull door clearance requirements. Inside the toilet rooms there is not enough clear floor space for a person in a wheelchair to turn around, transfer onto the toilet or open the door to exit. Also, the plumbing fixtures and several toilet accessories are not ADA compliant and the required grab bars are not provided.
- The Men's Toilet/Shower/Locker Rooms are lacking ADA compliant shower stalls.
- The Men's Toilet/Shower/Locker Rooms are lacking ADA compliant toilet stalls.
- Countertops do not meet ADA requirements in regard to maximum work surface height requirements. The countertop is too high for a person in a wheelchair to access.

#### **Bunk Room**

- There are (8) existing bunk areas separated by lockers.
   Bunk count does not meet current need for future growth.
   Existing bunks have required separation between individuals but does allows noise to easily reverberate throughout the entire room. Current trends have all 4 walls of the bunk room from floor to ceiling provided with sound insulation to reduce sound transfer, doors or door openings can be provided depending on the station's operation.
- The flow through the station is providing as direct as possible
  access to the Apparatus Bays in order to decrease response times
  for emergency calls. However, this results in a 'warm' zone
  directly off the Bays. Providing a better flow and buffer while still
  addressing direct response and access to the Bays would create a
  healthier environment and improve operations.

# Fire Station No. 21 Existing Condition Report















#### **Apparatus Bay**

- Apparatus Bays are a back-in style. The bays are tight based upon the original bay spacing. In addition, equipment and other storage is also located along the bay floor. This storage encroaches on egress aisles around vehicles and provides a safety concern.
- The Apparatus Bay is heated by two (2) gas fired unit heaters. The heaters are 80% efficient and are controlled by wall mounted thermostats.
- The Apparatus Bay contains a Plymovent exhaust capture system for the emergency vehicles. The Apparatus Bay also has a general exhaust fan mounted at the roof peak and ducted to a central exhaust grille. This fan is reported to be controlled by a wall switch but is not currently operational.
- There is currently no operating general exhaust system or gas
  detection system in the Apparatus Bay as required per current
  mechanical code. A gas detection system interlocked with the
  general exhaust system allows the exhaust system to operate
  intermittently or when CO/NO2 levels rise above the gas
  detection system set points. This issue needs to be addressed.
- A heavy-duty cast-iron trench drain serves the apparatus bay floor. The trench drain is connected to an oil separator (triple basin). The bay has one (1) hot and cold hose bib, two (2) general purpose hose connections and one (1) truck fill. Fixtures and equipment are in fair condition. Oil separator lid needs to be made gas tight, replace as required. The hose reels and truck fill do not have an RPZ to protect the potable water system. Add dedicated cold-water line and 2" RPZ for truck fill and hose reels.
- All existing light fixtures throughout the facility were replaced with more efficient LED light fixtures a couple years ago.
- The existing sectional overhead doors have cracked glazing seals and do not meet the current energy code. This condition results in a higher energy usage and cost for the Owner. Overhead doors appear to be at the end of their life expectancies and should be replaced soon.

## Fire Station No. 21 Existing Condition Report













#### **Apparatus Bay**

- The Apparatus Bay doors are only 12'-0" high, which limits what equipment can be stored at the station. The Department of Transportation standards recommends a minimum height of 13'-10" that will accommodate most equipment. This issue should be addressed.
- Turnout gear lockers are provided and installed along the walls of the bay. Locating gear directly on the bay floor exposes the personal protective equipment to UV lighting, fluorescent lighting, apparatus exhaust, and potential theft. This is a vital piece of protective equipment for the firefighter. Maintenance and proper storage are vital. Best practices say that this equipment should be housed in a separate room that can be shut off from most of the items listed above.
- A separate EMS Decon area is not provided. NFPA guidelines recommend an EMS Decon area be provided to wash and clean off pathogens and other contaminants from equipment after calls.
- Existing concrete slab cracking was observed in the Apparatus Bay. Floor cracking in the apparatus bays does not present a structural integrity issue but the issue should be addressed.
- Exposed concrete slab is in fair condition but has received years of stains after absorbing fossil fuels and chemicals. It is suggested that the concrete floor get coated with an epoxy system to seal the existing conditions of the slab, protect for future use and add slip resistance to the floor.

#### **Laundry Room**

• Existing residential laundry and gear wash extractor are located together off the main residence. Location of laundry room requires all staff to bring soiled residential and contaminated gear through the bays and into the residence areas. This conflicts with national guidelines and violates the 'hot' vs 'cold' zone separation. This issue needs to be addressed.

## Fire Station No. 21 Existing Condition Report













#### **Storage Rooms**

 Storage and supply rooms are undersized thus leaving the existing station cluttered. There is not a potential opportunity to reorganize, replace shelving or remove unused equipment to provide more storage space. Larger dedicated storage and mechanical rooms need to be provided.

#### Kitchen

- The kitchen for the station is undersized. Existing refrigerators are located in adjacent spaces because there is not space to locate them in the kitchen. Existing kitchen does not allow the proper space required for the typical food prep triangle.
- Existing countertops are plastic laminate with a composite wood core, this product at a wet surface location is not suggested due to possible delamination of the finish and deterioration of the composite wood core. It is suggested that all countertops in the kitchen be replaced with a more durable product like solid surface or quartz.
- Commercial hood in kitchen not provided with required make-up air unit. This issue needs to be addressed if hood is altered in the future.
- Sink base cabinet in the kitchen does not allow front approach wheelchair access as required per ADA. Sink base would need to be replaced with ADA compliant sink base.
- Kitchen Countertops do not meet ADA requirements in regard to reach range and maximum work surface height requirements. The countertop is too high for a person in a wheelchair to access.

# SECTION 5.1 Fire Station No. 21 Existing Condition Report















#### **Toilet Room**

- The toilet rooms do not meet ADA requirements in regard to reach ranges, plumbing fixture clearances, turning radius clearances and push/pull door clearance requirements. Inside the toilet rooms there is not enough clear floor space for a person in a wheelchair to turn around, transfer onto the toilet or open the door to exit. Also, the plumbing fixtures and several toilet accessories are not ADA compliant and the required grab bars are not provided.
- Toilet rooms are lacking ADA compliant toilet stalls.
- Countertops do not meet ADA requirements in regard to maximum work surface height and approach requirements. The countertop is too high for a person in a wheelchair to access.

#### Women's Toilet/Shower/Locker Room

- Elevation changes at gas curb between Women's
   Toilet/Shower/Locker Rooms and apparatus bay does not allow a
   handicapped employee or visitor to enter or safely egress out of
   the space as required by accessibility and building code. This issue
   needs to be addressed.
- The Women's Toilet/Shower/Locker Rooms do not meet ADA requirements in regard to reach ranges, plumbing fixture clearances, turning radius clearances and push/pull door clearance requirements. Inside the toilet rooms there is not enough clear floor space for a person in a wheelchair to turn around, transfer onto the toilet or open the door to exit. Also, the plumbing fixtures and several toilet accessories are not ADA compliant and the required grab bars are not provided.
- The Women's Toilet/Shower/Locker Rooms are lacking ADA compliant shower stalls.
- The Women's Toilet/Shower/Locker Rooms are lacking ADA compliant toilet stalls.
- Countertops do not meet ADA requirements in regard to maximum work surface height and approach requirements. The countertop is too high for a person in a wheelchair to access.

# SECTION 5.2 Fire Station No. 22 Existing Condition Report







#### Fire Station No. 22 - Existing Building Condition Report

Fire Station No. 22 was originally built in the 1970s. The existing building is a single-story facility with a basement. The first floor above the basement is precast concrete planks. Exterior walls are constructed of uninsulated single wythe masonry bearing walls. The existing ballasted membrane roof over the apparatus bays, bay support and residence are flat and supported by structural steel joists. The interior walls at this station are primarily CMU block partitions in the apparatus bay, bay support and residence areas.

#### Site and Parking

- Existing staff parking spaces for the facility are on the west side of the building and existing public convenience parking spaces for the facility are located at the main entry of the building. Current parking space count is sufficient for current needs.
- The asphalt parking and drives are in poor condition and have areas of cracking and should be replaced in the near future. If not replaced, water will continue to penetrate below the paved surface to the base and degrade the surface.
- The concrete apron has cracking at the control joints and should be replaced in the near future. If not replaced, water will continue to penetrate below the paved surface to the base and degrade the surface.
- Existing masonry trash enclosure gates appear to be in fair condition, but hardware is starting to fall apart and should be replaced in the near future. Steel bollards and framed gate doors should be provided in lieu of composite wood framing for longer life cycle and durability. Several areas of brick veneer were noted as having cracked grout joints at walls and limestone caps. These issues should be addressed by tuckpointing all of the exterior brick veneer walls and limestone caps or replacing limestone caps in kind or with aluminum coping.

# SECTION 5.2 Fire Station No. 22 Existing Condition Report













#### **Building Envelope:**

- The existing flat roof at the apparatus bays, bay support and residence are single ply ballasted roofing systems with rigid insulation and is supported by steel decking and bar joists. The roofing membrane appears to be in good condition after being recently repaired. Existing roof insulation appears to be half of the required amount based on today's construction standards and Energy Code requirements. This condition results in a higher energy usage and cost for the Owner and needs to be addressed.
- All areas of single wythe load bearing masonry was noted as having efflorescence and cracked or missing grout joints at walls of interior surfaces. Efflorescence typically can be seen on exterior faces of masonry walls due to water penetrating the wall from multiple sources such as parapets, and heads and sills of windows. Existing efflorescence on interior surface of masonry wall appears to be due to negative pressure drawing the moisture through the mortar and masonry and into the building. Though some areas appear to have been tuck pointed or caulked there were still many other areas that have been yet to be addressed. This issue needs to be addressed or the entire exterior load bearing wall will continue to deteriorate leading to potential structural issues. This issue involves the entire building, and there is simply no easy way to fully seal out moisture from entering the building and continuing to cause damage.
- Due to the time frame in which this single wythe masonry building
  was constructed and from reviewing the original construction
  drawings, the exterior walls contain no insulation. This condition
  does not meet today's construction standards and Energy Code
  requirements. This condition results in a higher energy usage and
  cost for the Owner and should be addressed.
- There are several interior and exterior steel lintels at window and door openings that appear to have started to rust at the surface and were painted. If not addressed soon these lintels will continue to deteriorate and potentially allow water to penetrate the cavity wall and lead to other issues. It is suggested that all steel lintels be sanded to remove paint and surface rust and receive the required primer/paint coats to seal and protect the steel.
- The existing aluminum clad wood windows appear to be in fair shape but are past their useful lifespan and have been wrapped and painted. It is suggested they be replaced with more energy efficient windows to reduce energy usage and cost for the Owner.

# Fire Station No. 22 Existing Condition Report











#### **Building Envelope:**

- The existing glass sectional overhead doors appear to have recently been painted and appear to be in good condition. No issues reported.
- All exterior grouted hollow metal frames and doors are in good condition but do not meet today's construction standards and Energy Code requirements. It is suggested that all exterior hollow metal doors and frames be replaced with insulated doors and thermally broken frames to reduce energy usage and cost for the Owner.

#### **Accessibility:**

Since the building was constructed and last renovated, accessibility requirements have changed with the Americans with Disabilities Act (ADA). The accessibility guidelines mandate that all public facilities are to be designed, constructed, or altered to assure equal accessibility to all members of society. If any type of renovation within the building occurs, multiple accessibility violations would need to be addressed. The violations range from minor issues to larger problems that would require significant renovation work. Below is a summary of violations reviewed during the building assessment:

#### Accessibility:

- All entrance/egress exits for the facility do not meet ADA requirements due to existing elevation changes at stoops that do not allow a handicapped visitor or employee to enter or exit the facility safely.
- No elevator, accessible stairs or ramps are provided that currently serve the facility. A handicapped visitor or employee cannot currently access the training/meeting room since it is in the basement.
- Existing stairs to basement do not have ADA required handrails.
   Also, handrails are not the proper shape or diameter and do not extend beyond the top and bottom risers the required 12". The guardrails and handrails would need to be replaced with new compliant guardrails and handrails.
- Egress paths to exit the facility do not meet ADA requirements due to doors swinging the wrong way that do not allow a handicapped visitor or employee to exit or travel through the facility safely.

# Fire Station No. 22 Existing Condition Report















#### Accessibility:

- All entrance/egress exits for the facility do not meet ADA requirements due to existing elevation changes at gas curbs that do not allow a handicapped visitor or employee to enter or exit the facility safely.
- Most doors entrance and exits to and from occupiable rooms along the path of egress do not have the required push/pull clear floor space provided that allows a handicapped visitor or employee to enter or exit the facility safely.
- Kitchen Countertops do not meet ADA requirements in regard to reach range and maximum work surface height requirements. The countertop is too high for a person in a wheelchair to access.
- All casework doors and drawers do not have ADA compliant pulls.
   These would need to be replaced with an ADA wire pull that does not require tight grasping or pinching to operate.
- Sink base cabinet in kitchen does not allow front approach wheelchair access as required per ADA. Sink base would need to be replaced with ADA compliant sink base.
- All toilet/shower rooms do not meet ADA requirements in regard to reach ranges, plumbing fixture clearances, turning radius clearances and push/pull door clearance requirements. Inside the toilet rooms there is not enough clear floor space for a person in a wheelchair to turn around, transfer onto the toilet or open the door to exit. Also, the plumbing fixtures and several toilet accessories are not ADA compliant and the required grab bars are not provided.
- All toilet/shower rooms are lacking ADA compliant shower stalls.
- All toilet/shower rooms are lacking ADA compliant toilets.
- Existing stairs, toilet rooms and exits do not meet ADA signage requirements, no signage is currently provided. The entire facility needs to be provided with ADA compliant rooms signage.
- Most door hardware throughout the building are knobs. These
  would need to be replaced with ADA compliant lever handles that
  do not require tight grasping, pinching, or twisting of the wrist to
  operate.

### Fire Station No. 22 Existing Condition Report









#### **Building Code Issues:**

- There is no elevator that services the facility. Currently, a
  handicapped visitor or employee cannot access the training room
  since it is in the basement. This issue needs to be addressed.
- The existing stair does not have ADA required hand and guard rails. Also, handrails are not the proper shape or diameter and do not extend beyond the top and bottom risers the required 12".
   The guardrails and handrails would need to be replaced with new compliant guardrails and handrails.
- There is not a code compliant egress path from the basement.
   Stair is not enclosed in fire rated construction, does not meet the minimum width requirement, and does not exit directly to the exterior. Two egress stairs are required for exiting. This issue needs to be addressed.

#### **NFPA Life Safety Code:**

The National Fire Prevention Association (NFPA) publishes a series of safety codes and standards devoted to minimizing the possibility of fire and other risks. As a public facility dedicated to minimizing fires and other risks, this Fire Station is required to follow the standards set forward by the NFPA Life Safety Code Standards. Below is a list of NFPA violations that were observed:

 There is no NFPA 72 compliant gas detection system within the Apparatus Bay.

NFPA 1851 lays out the guidelines for handling elements that have been contaminated with hazardous materials. Many of the standards are related to standard operating procedures that need to be developed by the Fire Department. However, some of the procedures also require physical spaces that need to be integrated into the existing building. Listed below are some of the observed violations of NFPA 1851 due to space limitations within the current facility:

 To prevent cross contamination, a designated decontamination area is required for routine cleaning of personal protective equipment that has been in contact with hazardous materials.
 There is no dedicated decontamination room observed within the current facility, all fire gear is being stored on the Apparatus Bay floor.

## Fire Station No. 22 Existing Condition Report







#### **First Floor Interior:**

#### **General Notes**

- Most of the facility has 2'x4' acoustical ceiling tiles that appear to be in good condition. All existing light fixtures throughout the facility were replaced with more efficient LED light fixtures a couple years ago.
- The countertops are plastic laminate, this product type at a wet surface location is not suggested due to possible delamination of the finish and deterioration of the composite wood core. It is suggested that all countertops in toilet rooms and kitchen be replaced with a more durable product like solid surface or quartz.

#### Mechanical system:

- Existing mechanical system comprised of three (3) Carrier furnaces. Each furnace is gas fired, standard efficiency, up flow configuration. The furnaces have associated humidifiers and cooling coils. The associated condensing units are located on grade at the north face of the building.
- One furnace serves the lower level. Ductwork is routed at the ceiling with ceiling supply and return diffusers. The second furnace serves the ground level east side. Ductwork is routed at the lower-level ceiling with supply stubs up to floor registers, the return duct is routed up to the 1st floor ceiling with sidewall return grilles. The third furnace serves the ground level west side. Ductwork is routed at the lower-level ceiling with supply stubs up to floor registers, the return duct is routed up to the 1st floor ceiling with sidewall return grilles. Most of the floor supply registers are in fair to poor condition.
- The expected useful life of the furnaces is 18 years. The furnaces are approximately 4 years old and appear to be in good condition. The expected useful life of the condensing units is 18 years. The condensing units are approximately 10 years old and appear to be in fair condition.

## Fire Station No. 22 Existing Condition Report











#### **Plumbing Systems:**

#### Sanitary

• The underground sanitary waste and vent system is hub and spigot cast iron. The above grade sanitary waste and vent system is generally hub and spigot cast iron (3" and larger) and galvanized pipe (2" and smaller). Exposed piping appears to be in good condition; however, given the age of the facility, it is unlikely that the interior of the galvanized piping is still in good condition. It is suggested that the existing sanitary system be inspected (camera) and cleaned (rodding acceptable, jetting preferred) to increase the life expectancy of the system.

#### Interior

- The fire suppression service is ductile iron pipe while the domestic service is copper. The water piping is generally copper pipe with soldered joints. The building has a 2" water meter, a 2" RPZ for potable water. The fire protection system (truck fills & sprinkler heads) has a 4" double detector check. Isolation valves were not observed at fixture groups. Isolation valves should be installed when construction requires it.
- The mechanical room consists of an atmospheric natural gas water heater, a duplex sewage ejector pump system, a duplex sump pump system, one (1) service sink and a floor drain. The water heater is 98 gallons, 75,100 BTUH. The 2" water service and associated 2" RPZ are also located in the room. There is an unused water stub inside the room. Code requires dead ends be less than 2'-0" in length, reduce as required.

#### **Exterior**

 The building's exterior has two (2) wall hydrants and scupper system for overflows. The wall hydrants appear to be in fair to good condition.

## Fire Station No. 22 Existing Condition Report









#### **Electrical System:**

- The electrical service to the building is an underground type rated at 400-amps, 120/208v, three phase system, the meter is in the electrical room. The building is backed-up by a generator. During power loss, the Automatic Transfer Switch (ATS) is located in the electrical room and transfers power from normal (ComEd) power to Emergency (generator) power. The electrical service has a spare capacity of 266 amps for minor future expansion.
- The electrical service is registered with ComEd. Per ComEd's record the peak demand occurred in January 2022 with 27.80 KW (134 amps).

#### Fire Alarm System:

 Existing Notifier fire alarm panel is located in the mechanical/electrical room. Pull stations are provide as required. Existing system appears to be regularly serviced and in good working conditions but is also out of date and does not meet current code requirements. Existing fire alarm system and fire alarm devices to be replaced as required to meet current codes.

#### **General Notes:**

- Most of the facility has 2'x4' acoustical ceiling tiles that appear to be in good condition. Some stained and damaged tiles should be replaced.
- All existing light fixtures throughout the facility were replaced with more efficient LED light fixtures a couple years ago.
- The countertops are plastic laminate, this product type at a wet surface location is not suggested due to possible delamination of the finish and deterioration of the composite wood core. It is suggested that all countertops in toilet rooms and kitchen be replaced with a more durable product like solid surface or quartz.

### Fire Station No. 22 Existing Condition Report













#### **Interior First Floor:**

#### Vestibule

- Main entrance is narrow and undersized, visitors enter into a small corridor and then move into main intersection of station corridors. A more inviting entry should be reviewed, at a minimum the vestibule should be widened.
- Tile flooring appears to be original to the building and is reaching the end of its lifespan. It is suggested that flooring be replaced.
   The CMU appears to have been painted recently.

#### **Station Corridors**

- Most door access and exits to and from occupiable rooms along the path of egress do not have the required push/pull clear floor space provided that allows a handicapped visitor or employee to enter or exit the facility safely.
- There is not a code compliant egress path from the basement.
   Stair is not enclosed in fire rated construction, does not meet the minimum width requirement, and does not exit directly to the exterior. Two egress stairs required for exiting. This issue needs to be addressed.
- Carpet flooring appears to be original to the building and is reaching the end of its lifespan. It is suggested that carpet flooring be replaced with a more resilient material that can hold up to boot traffic better like tile or vinyl. The CMU appears to have been painted recently.

#### **Officer Suite**

- Office appears to be correctly sized, but bunk and toilet room are undersized. Required area for workstation and file storage provided. Office connected to toilet and bunk to form a suite. Flow between spaces is less than desirable, this issue should be addressed.
- All toilet/shower rooms do not meet ADA requirements in regard to reach ranges, plumbing fixture clearances, turning radius clearances and push/pull door clearance requirements. Inside the toilet rooms there is not enough clear floor space for a person in a wheelchair to turn around, transfer onto the toilet or open the door to exit. Also, the plumbing fixtures and several toilet accessories are not ADA compliant and the required grab bars are not provided.

## Fire Station No. 22 Existing Condition Report











- Toilet/shower room is lacking ADA compliant shower stalls.
- All toilet/shower rooms are lacking ADA compliant toilet stalls.
- Sinks in toilet/shower rooms do not allow front approach wheelchair access as required per ADA. Sink base/counter tops would need to be replaced with ADA compliant sink bases.
- Tile appears to be original to the building and is reaching the end of its lifespan. It is suggested that flooring be replaced.

#### Officer Bunks

- (2) officer bunks are combined to house (2) joined bunk areas provided with (3) beds and (9) lockers.
- Bunk room does not provide space for ADA compliant turning radius and push/pull door clearance requirements that allows safe entrance and egress from the space.
- Tile flooring appears to be original to the building and is reaching the end of its lifespan. It is suggested that flooring be replaced.
   CMU appears to have been painted recently.

#### **Communication Room**

- Communication room is undersized for the station's operations.
   More room for additional workstations and conference table should be provided if possible.
- Carpet flooring appears to be original to the building and is reaching the end of its lifespan. It is suggested that carpet flooring be replaced with a more resilient material that can hold up to boot traffic better like tile or vinyl. CMU appears to have been painted recently.

#### Men's Locker Room

 All toilet/shower rooms do not meet ADA requirements in regard to reach ranges, plumbing fixture clearances, turning radius clearances and push/pull door clearance requirements. Inside the toilet rooms there is not enough clear floor space for a person in a wheelchair to turn around, transfer onto the toilet or open the door to exit. Also, the plumbing fixtures and several toilet accessories are not ADA compliant and the required grab bars are not provided.

### Fire Station No. 22 Existing Condition Report







- All toilet/shower rooms are lacking ADA compliant shower stalls.
- All toilet/shower rooms are lacking ADA compliant toilet stalls.
- Sinks in toilet/shower rooms and kitchen do not allow front approach wheelchair access as required per ADA. Sink base/counter tops would need to be replaced with ADA compliant sink base.
- Countertops do not meet ADA requirements in regard to maximum work surface height requirements. The countertop is too high for a person in a wheelchair to access.
- Tile flooring appears to be original to the building and is reaching the end of its lifespan. It is suggested that flooring be replaced.
   CMU appears to have been painted recently.

#### **Kitchen**

- The kitchen for the facility is undersized. Tile flooring appears to be original to the building and is reaching the end of its lifespan. It is suggested that flooring be replaced. The CMU walls appear to have been painted recently. Stainless steel countertops appear to be in good condition. With all the hard surfaces noted in this area, sound reverberance should be addressed in the Kitchen/Dayroom/Dining.
- Sink base cabinet in the kitchen does not allow front approach wheelchair access as required per ADA. Sink base would need to be replaced with ADA compliant sink base.
- Kitchen Countertops do not meet ADA requirements in regard to reach range and maximum work surface height requirements. The countertop is too high for a person in a wheelchair to access.
- All casework doors and drawers do not have ADA compliant pulls.
   These would need to be replaced with ADA wire pulls that do not require tight grasping or pinching to operate.

#### Dayroom

 Dayroom appears to be slightly undersized. Seating arrangement in the space is not desirable. New room layout and furniture arrangement to be reviewed to increase monitor sight lines.

# SECTION 5.2 Fire Station No. 22 Existing Condition Report













#### **Bunk/Locker Room**

- There are eight (8) existing bunk areas separated by curtains.
   Bunk count does not meet current need or future growth. Existing bunks to do allow required separation between individuals and allows noise to easily reverberate throughout the entire room.
   Current trends have all 4 walls of the bunk room from floor to ceiling and provide sound insulation to knock down sound transfer, doors or door openings can be provided depending on the station's operation.
- Twenty-four (24) lockers are provided, this is not enough to meet future growth. Additional lockers need to be provided. Current trends have the lockers either located in the individual bunk rooms or in a combined locker room with toilet/shower rooms directly located off the locker room to allow for individual changing space.
- Carpet flooring appears to be original to the building and is reaching the end of its lifespan. It is suggested that carpet flooring be replaced.

#### **Apparatus Bays**

- Apparatus Bays are a back-in style. The bays are tight based upon the original bay spacing. In addition, equipment and other storage is also located along the bay floor. This storage encroaches on egress aisles around vehicles and provides a safety concern. The lack of storage for the bay, seasonal, training and public ed needs to be addressed.
- Apparatus bay is heated by four (4) gas fired unit heaters. The
  heaters are 80% efficient and are controlled by wall mounted
  thermostats. The expected useful life of the Apparatus Bay unit
  heaters is 13 years. The exact age of the unit heaters is not
  known; however, they are relatively new and appear to be in good
  condition.
- The Apparatus Bay contains a Plymovent exhaust capture system for the emergency vehicles. The Apparatus Bay also has a general exhaust fan mounted on the roof and ducted to a central exhaust grille. This fan is controlled by a wall switch but is not currently operational.
- The Generator Room, Workshop and Hose Drying room each have a gas fired unit heater, controlled by wall mounted thermostats. The Hose Drying room and Workshop each has exhaust ducted to a roof mounted exhaust fan. The dryer exhaust is ducted to an exterior wall louver.

## Fire Station No. 22 Existing Condition Report











#### **Apparatus Bays**

- There is currently no operating general exhaust system or gas detection system in the Apparatus Bay. Code requires a minimum of 0.75 CFM/sq.ft exhaust. A gas detection system interlocked with the general exhaust system allows the exhaust system to operate intermittently or when CO/NO2 levels rise above the gas detection system setpoints.
- All existing light fixtures throughout the facility were replaced with more efficient LED light fixtures a couple years ago.
- The Apparatus Bay doors are only 12'-0" high, which limits what equipment can be stored at the Station. The Department of Transportation standards recommends a minimum height of 13'-10" that will accommodate most equipment. This issue should be addressed.
- Existing concrete slab cracking was observed in the Apparatus Bay. Floor cracking in the apparatus bays does not present a structural integrity issue but the issue should be addressed.
- Epoxy flooring is in fair condition but has received years of stains
  after absorbing fossil fuels and chemicals and is deteriorating. It is
  suggested that the concrete floor get coated with a new epoxy
  system to seal the existing conditions of the slab and protect for
  future use. Epoxy floor systems also provide slip resistance.
- Turnout gear lockers are provided and installed along the walls of the bay. Locating gear directly on the bay floor exposes the personal protective equipment to UV lighting, fluorescent lighting, apparatus exhaust, and potential theft. This is a vital piece of protective equipment for the firefighter. Maintenance and proper storage are vital. Best practices say that this equipment should be housed in a separate room that can be shut off from most of the items listed above.
- All personal and gear laundry is done on the bay floor, this poses issues for contamination between clean and dirty spaces. Clean towels and other items are stored on the bay floor. To prevent cross contamination, a designated decontamination area is required for routine cleaning of personal protective equipment that has been in contact with hazardous materials.

### Fire Station No. 22 Existing Condition Report







#### **Apparatus Bays**

- Heavy-duty cast-iron trench drains serve the apparatus bay floor. The trench drain is connected to an oil separator (triple basin). The bay has one (1) service sink with standard trap, two (2) washing machines, one (1) ice machine, two (2) general purpose hose connections and two (2) 2" truck fills. Reseal oil separator to make it airtight and provide vent at washing machine waste line.
- The flow through the station is providing as direct as possible
  access to the Apparatus Bays in order to decrease response times
  for emergency calls. However, this results in a 'warm' zone
  directly off of the Bays. Providing a better flow and buffer while
  still addressing direct response and access to the Bays would
  create a healthier environment and improve operations.

#### **Lower Level:**

#### **Training Room**

- Existing training room is severely undersized. Existing training room was designed to seat twelve (12) but needs to accommodate thirty (30) at weekly training sessions. To correctly accommodate the current space needs for training, this space needs to be larger.
- No training storage room is provided adjacent to the training room, storage cabinets line the walls. By not having a separate storage room this undersized room is even less usable due to training tools and equipment occupying the already limited space.
- Carpet flooring appears to be original to the building and is reaching the end of its lifespan. It is suggested that carpet flooring be replaced with a more resilient material that can hold up to boot traffic better like tile or vinyl. CMU walls appear to have been painted recently.

#### **Conference Room**

- Conference room/report writing/workstations are provided in the basement. These spaces do not appear to be regularly used but should be located adjacent to other operational type spaces.
- Carpet flooring appears to be original to the building and is reaching the end of its lifespan. It is suggested that carpet flooring be replaced with a more resilient material that can hold up to boot traffic better like tile or vinyl. CMU walls appear to have been painted recently.

### Fire Station No. 22 Existing Condition Report







#### **Fitness**

- Fitness room is undersized for the Department's desired use of the fitness room. Flooring is not rated for fitness applications.
   A sports floor is typically suggested for fitness applications.
- Ceiling height is a bit lower than desired, current fitness trends have larger equipment and requires taller ceiling clearance.

#### **Women's Locker Room**

- All toilet/shower rooms do not meet ADA requirements in regard to reach ranges, plumbing fixture clearances, turning radius clearances and push/pull door clearance requirements. Inside the toilet rooms there is not enough clear floor space for a person in a wheelchair to turn around, transfer onto the toilet or open the door to exit. Also, the plumbing fixtures and several toilet accessories are not ADA compliant and the required grab bars are not provided.
- Toilet/shower room is lacking ADA compliant shower stalls.
- The Toilet/shower room is lacking an ADA compliant toilet stall.
- Sinks in toilet/shower room do not allow front approach wheelchair access as required per ADA. Sink base/counter tops would need to be replaced with ADA compliant sink base.
- Tile appears to be original to the building and is reaching the end of its lifespan. It is suggested that flooring be replaced.

#### **SECTION 6**

### Fire Station No. 21 & No. 22 Existing Conditions Analysis

#### **Existing Conditions Analysis of Station No.21 & No.22:**

The analysis of Fire Station No. 21 & No. 22 focused on 5 major points of concern:

- Systems, equipment, and spaces/ functions that the facility should have with regards to current Fire Service standards and recommendations
- 2. Spaces the current Fire Station is lacking because of the size of the existing facility.
- 3. Relationships/interconnection & separation/isolation of spaces.
- 4. Building envelope issues/ concerns and structural deficiencies
- 5. Miscellaneous comments/issues

Items were also evaluated on a life safety basis. Certain items should be completed sooner than others, based upon the impact they have on the safety of the occupants, officers, firefighters, or public.

This classification approach is shown to provide a minimum amount of work required to get the current facilities safe for its occupants. It helps define each item according to operations and need. Ultimately, it helps the Village plan on how best to address points of concern throughout the facility. However, correcting each safety item will still not address any space shortcomings in the building.

By evaluating and making recommendations to address the current building conditions, a baseline cost impact is established to bring the building up to current standards. It is anticipated these improvements will extend the buildings' lifespans by another 15 to 20 years. However, none of the space or operational deficiencies are corrected with these costs.

The total cost impact of improving the existing building conditions:

Station 21: Low \$2,000,000

High \$3,000,000

Station 22: Low \$3,500,000

High \$4,500,000

These are significant costs and, as was noted above, do not account for any additional square footage added to the buildings or ancillary costs such as furniture/fixture replacements. The other important factor to note is how undersized each facility is:

Station 21: Current 6,175 sq.ft.

Proposed 13,562 sq.ft.

Station 22: Current 11,534 sq.ft.

Proposed 25,296 sq.ft.

The next section of the report, potential solutions, will analyze on how best to solve each station's situation to meet the Department's future needs highlighted throughout this study.

#### **SECTION 7**

Fire Station No. 21 & No. 22 & Fire Department Administration Potential Solutions

#### **Potential Solutions**

The Potential Solutions studied include the following:

#### 7.1 Fire Station No.21

Solution A - A new station on the existing site
Solution B - A new station located south of the police facility
Solution C - A new station located to the north of the police
facility within the existing parking lot

#### 7.2 Fire Station No.22

Solution A - A new station on the existing site
Solution B - A new station on the vacant site along Barrington
Road
Solution C- A new station located within the Northwest Corporate
Center

#### 7.3 Fire Department Administration

Evaluation of department relocation

On the following pages are descriptions, plan diagrams, and budgets of each concept explored.

### Fire Station No. 21 Solution A

#### **SOLUTION A:**

This solution shows a new proposed station rebuilt on the existing site at 225 Flagstaff Lane. Due to the increased proposed size of 13,562 sq.ft. the building does not fit within the existing property and setback lines. However, the adjacent park property is owned by the Village so additional property can be allocated along the eastern property line.

In order to accommodate the larger station, an additional .2 acres would be needed to fit the building in this location. It must be noted that the proposed 1-acre site would fit the building and associated parking and drives but no water detention has been identified.

This solution allows the station to remain in its current location, but a temporary relocation would be necessary for the operations of the station while construction is being completed. Decisions on where responders could be relocated would need to be determined by the Village. Potential options include moving into a neighboring fire department, relocating to a nearby industrial storage or vacant building, or relocate to a temporary trailer and hoop structure for the apparatus. These temporary situations could add an additional \$250,000 to the project cost.

Alternately, since the Village owns the adjacent park, a new station could be built in the park, which would allow operations to continue in the existing facility during construction.

#### HOFFMAN ESTATES FD STATION 21

225 FLAGSTAFF LN, HOFFMAN ESTATES, IL 60169



SITE PLAN DIAGRAM A

HOFFMAN ESTATES FIRE DEPARTMENT Published 11/07/22
Job No. 22-3489.01 ©2022 FGM Architects Inc.



Fire Station No. 21 Solution B

#### **SOLUTION B:**

This solution shows a new proposed station built on the south side of the existing police facility located at 411 W Higgins. The 13,562 sq.ft. building is shown attached to the south entrance area of the police facility. The building does fit within the exiting property and setback lines; however, the size of the building would prohibit the current circular traffic pattern completely around the police facility. It also encroaches into the detention area along the south property line.

This solution allows the new station to be built while operations remain active at the current facility.

Based on the discussion above, this solution is not a preferred option.

### HOFFMAN ESTATES FD STATION 21



SITE PLAN DIAGRAM B

HOFFMAN ESTATES FIRE DEPARTMENT Job No. 22-3489.01

Published 11/07/22 @2022 FGM Architects Inc.



Fire Station No. 21 Solution C

#### **SOLUTION C:**

This solution shows a new proposed station built on the north side of the existing police facility located at 411 W Higgins. The 13,562 sq.ft. building is located in the existing parking lot to the north of the police facility. The building does fit within the exiting property and setback lines.

The existing parking lot would need to be reconfigured and an analysis of parking lot spaces for the whole site performed. Consideration must also be given to the adjacent church sharing the lot. This location will alter the presence of the police station from the corner intersection but will provide a public safety campus arrangement.

This solution also allows the new station to be built while operations remain active at the current facility. Per the location analysis, this site is a recommended option based solely on location.

### **HOFFMAN ESTATES FD STATION 21**

WEST HIGGINS RD

SITE PLAN DIAGRAM C

HOFFMAN ESTATES FIRE DEPARTMENT Job No. 22-3489.01

Fire Station No. 21 & No. 22 Study

#### **SECTION 7.1**

### Fire Station No. 21 **Budget**

#### **Station No. 21 Budget:**

This page represents the budget for a new station as indicated in any of the solutions shown for Station No. 21.

### **Village of Hoffman Estates**

New Fire Station No. 21

#### DRAFT

**FGMA**RCHITECTS

New Fire Station No. 21	DRAFT	March 29, 2023
Station Study - Project Budget		FGM#: 22-3489.01

	Item	Quantity	Unit		Cost	-			Construc	tion	Cost	Remarks
				L	.ow		High		Low		High	
.0	NEW FIRE STATION CONSTRUCTION											Costs include building and ordinary site work
.1	New Station Construction	13,562		\$	450		470	-	6,102,900	-	6,374,140	
.2	Existing Station Demolition	13,562	s.f.	\$	13	\$	15		176,306		203,430	
.3	Sub-Total Fire Station Construction			-				\$	6,279,206	\$	6,577,570	
.0	Design and Construction Contingency (10%)							\$	627,921	\$	657,757	
3.0	Total Fire Station Construction Budget							\$	6,907,127	\$	7,235,327	Includes contingency
.0	Allowances for Items to be Purchased by the Owner											
.1	Furniture and Furnishings							\$	50,000	\$	75,000	
.2	Window Treatments							\$	7,500	\$	15,000	
1.3	Kitchen/Laundry Equipment							\$	35,000	\$	40,000	
1.4	Radio and Station Alerting Equipment							\$	35,000	\$	45,000	
1.5	Fitness Equipment							\$	-	\$	-	by foreign fire?
.6	Computer Systems							\$	10,000	\$	15,000	
1.7	Wireless Network System							\$	10,000	\$	15,000	
1.8	Maintenance/Janitorial Equipment							\$	2,500	\$	5,000	
1.9	Telephone System							\$	10,000	\$	15,000	
.10	Wireless Telephone Boosters/Amplifiers							\$	-	\$	-	
.11	Miscellaneous Equipment and Furnishings							\$	10,000	\$	20,000	For items such as plaques, displays, art, etc.
1.12	Total Allowances for Items to be Purchased by the Owner							\$	170,000	\$	245,000	
5.0	Allowances for Items Fees and Soft Costs											
5.1	Architectural and Engineering Fees (10%)							\$	627,921	ċ	657 757	Incl. Struct, MEP&FP, Civil, Landscape
5.3	Surveys & Soil Investigations							\$	8,000		10,000	inci. Struct, WEI &IT, CIVII, Lanuscape
5.4	Material Testing During Construction							\$	15,000		20,000	
5.5	Building Commissioning							\$	15,000	-		Basic Commissioning - reg'd by code
5.6	Printing Costs							\$	1,500	-	2,000	Basic Commissioning - req u by code
5.8	Utility Company Charges (Electric, Gas, Telephone, Water)							\$	50,000		75,000	
5.9	Fiber Optic Service Provider							\$	-	\$	73,000	
	Moving Costs							ڔ	TBD	۰	TBD	
	Utility costs during construction							\$	15,000	ċ	25,000	
	Total Allowances for Fees and Soft Costs							\$	732,421		809,757	
6.0	Owner's Contingency (5%)					H		\$	313,960	Ś	328.879	5% of Construction Cost Sub Total
								Ė				
7.0	TOTAL FIRE STATION BUDGET							\$	8,123,508	\$	8,618,963	
3.0	Inflation per annum (4%)							\$	324,940	\$	344,759	1 year of interest. Add 4% for each add. year
3.1	2025 Construction Cost							\$	8,448,448	\$		build in 2025
9.0	Notes:											
9.1	The budget is based upon a construction start in 2024.											

9.3 The budget for this project is preliminary and is based on historical information. These costs may vary significantly as the project becomes more fully developed.

Estimate excludes: land purchase, premium costs for work done in phases, out of sequence, out of normal working hours, hazardous material removal, foundation obstructions, traffic

9.4 signalization costs, environmental costs which are unknown at this time, extraordinary site development costs.

Project Budgets do not include legal fees or financing costs.

9.6 Construction Costs are based utilizing a Design-Bid-Build project delivery method.

### Fire Station No. 22 Solution A

#### **SOLUTION A:**

This solution shows a new proposed station built on the existing site located at 1700 Moon Lake Blvd. The proposed 25,296 sq.ft. building is more than double the size of the existing facility. Even though the diagram illustrates a single-story layout, a multi-story facility would still be difficult to fit on the current site and would add to the overall cost and increase the size due to required stairs and elevator. The building does not fit within the existing property and setback lines. Required parking and drives become extremely difficult to accommodate on this site.

The current 1.4-acre site is sloped along the north and west property lines so it will make it difficult to build in those areas. The size and proportions of the current property make it very difficult for this to be a viable option for a new expanded station.

This solution would also require a temporary relocation for the operations of the station while construction is being completed. Decisions on where responders could be relocated would need to be determined by the Village. Potential options include moving into a neighboring fire department, relocating to a nearby industrial storage or vacant building, or relocate to a temporary trailer and hoop structure for the apparatus. These temporary situations could add an additional \$250,000 to the project cost.

#### **HOFFMAN ESTATES FD STATION 22**

1700 MOON LAKE BLVD., HOFFMAN ESTATES, IL 60169







Published 11/07/22 ©2022 FGM Architects Inc



Fire Station No. 22 Solution B

#### **SOLUTION B:**

This solution shows a new proposed station built on a random vacant location within the identified location area. The proposed 25,296 sq.ft. building is more than double the size of the overall site. The building barely fits within the exiting setback lines and there is no additional room for parking and drives.

Per the location analysis, this site is not a recommended option based on its location. We do not recommend any further consideration of sites in this area.

### **HOFFMAN ESTATES FD STATION 22**

1700 MOON LAKE BLVD., HOFFMAN ESTATES, IL 60169



SITE PLAN DIAGRAM B





Fire Station No. 22 **Solution C** 

#### **SOLUTION C:**

This solution shows a new proposed station built on a site randomly selected along Higgins Road in order to be able to perform geographical location analysis calculations. The site is more than ample to fit the proposed 25,296 sq.ft. building. The location analysis is in the Executive Summary and the Addendum.

This solution allows the new station to be built while operations remain active at the current facility. Per the location analysis this site is a recommended option based solely on location.

One potential drawback to this location is that there is some risk involved exiting onto Higgins Rd.

#### HOFFMAN ESTATES FD STATION 22



SITE PLAN DIAGRAM C

HOFFMAN ESTATES FIRE DEPARTMENT Job No. 22-3489.01 Published 03/13/23 ©2023 FGM Architects Inc.



## Fire Station No. 22 Budget

Construction Costs are based utilizing a Design-Bid-Build project delivery method.

#### Station No. 22 Budget:

This page represents the budget for a new station as indicated in any of the solutions shown for Station No. 22.

#### **FGMARCHITECTS Village of Hoffman Estates** New Fire Station No. 22 DRAFT Station Study - Project Budget FGM#: 22-3489.01 Item Quantity Unit Cost/Unit **Construction Cost** Remarks Low High High 1.0 NEW FIRE STATION CONSTRUCTION Costs include building and ordinary site work New Station Construction 25,296 \$ 440 \$ 460 \$ 11,130,240 \$ 11,636,160 1.1 **Sub-Total Fire Station Construction** \$ 11,130,240 \$ 11,636,160 Design and Construction Contingency (10%) \$ 1,113,024 \$ 1,163,616 \$ 12,243,264 \$ 12,799,776 Includes contingency **Total Fire Station Construction Budget** 3.0 Allowances for Items to be Purchased by the Owner 4.1 Furniture and Furnishings 125.000 S 150.000 4.2 Window Treatments 15,000 20,000 55,000 Kitchen/Laundry Equipment 45.000 4.3 4.4 Radio and Station Alerting Equipment 45,000 \$ 55,000 4.5 Fitness Equipment by foreign fire? 4.6 Computer Systems Ś 15.000 \$ 20.000 47 Wireless Network System 15,000 \$ 20.000 2,500 4.8 Maintenance/Janitorial Equipment 5.000 4.9 Telephone System Ś 15,000 \$ 20,000 4.10 Wireless Telephone Boosters/Amplifiers 4.11 Miscellaneous Equipment and Furnishings 15,000 25,000 For items such as plaques, displays, art, etc. 4.12 Total Allowances for Items to be Purchased by the Owner 292.500 S 370.000 5.0 Allowances for Items Fees and Soft Costs Architectural and Engineering Fees (10%) 1.113.024 \$ 1,163,616 Incl. Struct, MEP&FP, Civil, Landscape 5.1 5.3 Surveys & Soil Investigations 10.000 5 4 Material Testing During Construction 25 000 30,000 5.5 Building Commissioning 20,000 \$ 22,500 Basic Commissioning - req'd by code Printing Costs 1,500 5.6 \$ 2,000 Utility Company Charges (Electric, Gas, Telephone, Water) 5.8 Ś 50.000 75.000 Fiber Optic Service Provider 5.9 TBD 5.10 Moving Costs 5.11 Utility costs during construction 20,000 30,000 5.12 Total Allowances for Fees and Soft Costs 1,239,524 \$ 1,343,116 6.0 Owner's Contingency (5%) 556,512 \$ 581,808 5% of Construction Cost Sub Total **TOTAL FIRE STATION BUDGET** \$ 14,331,800 \$ 15,094,700 7.0 Inflation per annum (4%) 573,272 \$ 603,788 1 year of interest. Add 4% for each add. year 8.0 2025 Construction Cost \$ 14,905,072 \$ 15,698,488 build in 2025 8.1 9.0 Notes: The budget is based upon a construction start in 2024. The budget for this project is preliminary and is based on historical information. These costs may vary significantly as the project becomes more fully developed. Estimate excludes: land purchase, premium costs for work done in phases, out of sequence, out of normal working hours, hazardous material removal, foundation obstructions, traffic signalization costs, environmental costs which are unknown at this time, extraordinary site development costs. Project Budgets do not include legal fees or financing costs.

Fire Station No. 21 & No. 22 Study

#### **SECTION 7.3**

## Fire Department Administration Analysis

#### **Analysis:**

The fire department administration was initially analyzed for the potential of it moving out of the Village Hall and into one of the fire stations being considered. The current administration "suite" shares many spaces and functions with other Village Hall departments so the relocation would necessitate an additional 6,243 sq.ft. to any of the potential solutions.

It was found that the actual offices and rooms within the administrative area are for the most part sized correctly. It was noted that there is not a need for additional space for other functions at the Village Hall so the relocation of fire administration would be solely based on the operational desires of the Fire Department to move to one of the fire stations.

#### **SECTION 8**

### Fire Station No.21 & No.22 Conclusion/ Summary

Our team conducted a fire station feasibility and needs study for the Village of Hoffman Estates Fire Department. The purpose of the study was to review current fire station locations and facilities, and to provide long-term recommendations for fire station needs, locations and infrastructure, taking into consideration response trends, planned or potential Village growth, and best practices in today's fire/rescue/EMS services.

The Village recognizes that Station No. 21 and No. 22 are in need of a significant investment. Before the Village makes decisions related to such an investment, FGMA and IFCA reviewed the existing facilities to ensure the Village makes the best use of its resources.

Both stations have been well maintained over the years, but they are past their useful life expectancies. Their current conditions and the required additional space needs necessitate the replacement of both stations.

#### Station No. 21:

There are two viable options for the Village to choose for this station. It can either be re-built in its current location (or on Village-owned adjacent land) or in the parking lot of the police station. Both options will cost between \$8.1 and \$8.7 million.

#### Station No. 22:

The recommended option for this station is to build a new facility in the identified ideal location area. This option will cost between \$14.3 and \$15.1 million for construction (excludes land acquisition costs).

This study is to be utilized as a starting point and is intended to provide the Village of Hoffman Estates with the necessary information to make an informed decision on which direction should be taken to address the location and space needs for Fire Stations No 21 & No 22.

Fire Station No. 21 & No. 22 Study

### **APPENDIX**

**Analytics Addendum** 



## **Station Location Analysis**

## Hoffman Estates Fire Department

2023







## **TERMS OF USE**

Illinois Fire Chiefs Association (IFCA) prepared this report which contains confidential and proprietary trade secrets and commercial information of the IFCA and may not be disclosed or republished by anyone other than the client organization. Violation of the confidentiality of this record will cause significant financial harm to the Illinois Fire Chiefs Association.

This report is the copyright of the Illinois Fire Chiefs Association which is protected by State and Federal copyright laws. No part of the document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronically or mechanically, photocopying or scanning this document without prior written permissions of the Illinois Fire Chiefs Association is strictly prohibited. The use, reproduction, downloading or distribution may subject you to the applicable penalties and damages under State and Federal copyright laws.





Definitions	1
Definitions	2
Domographics	2
Demographic Overview	3
Demographic Overview	4
Demographic - TRA	5
Demographic - AoR 21	6
Demographic - AoR 22	7
Demographic - AoR 23	8
Demographic - AoR 24	9
Service Area	10
Service Area Overview	11
Area Served by Drive Times - TRA	12
4 min and 8 min Drive Times - TRA	13
Streets Covered by Drive Times - TRA	14
Area Served by Drive Times - AoR 21	15
4 min and 8 min Drive Times - AoR 21	16
Streets Covered by Drive Times - AoR 21	17
TRA Coverage - AoR 21	18
Area Served by Drive Times - AoR 22	19
4 min and 8 min Drive Times - AoR 22	20
Streets Covered by Drive Times - AoR 22	21
TRA Coverage - AoR 22	22
Area Served by Drive Times - AoR 23	23
4 min and 8 min Drive Times - AoR 23	24
Streets Covered by Drive Times - AoR 23	25
TRA Coverage - AoR 23	26
Area Served by Drive Times - AoR 24	27
4 min and 8 min Drive Times - AoR 24	28
Streets Covered by Drive Times - AoR 24	29
TRA Coverage - AoR 24	30





Stu	dy Incidents	31
	All Incidents	32
	Inside TRA Incidents	33
	Outside TRA Incidents	34
	NFIRS Group - 100	35
	NFIRS Group - 200	36
	NFIRS Group - 300	37
	NFIRS Group - 400	38
	NFIRS Group - 500	39
	NFIRS Group - 600	40
	NFIRS Group - 700	41
	NFIRS Group - 800	42
	NFIRS Group - 900	43
Inci	dents by NFIRS Code	44
	TRA	45
	AoR 21	46
	AoR 22	47
	AoR 23	48
	AoR 24	49
Inci	dents Hotspots	50
	NFIRS Group 100 - 900	51
	NFIRS Group 100	52
	NFIRS Group 200	53
	NFIRS Group 300	54
	NFIRS Group 400	55
	NFIRS Group 500	56
	NFIRS Group 600	57
	NFIRS Group 700	58
	NFIRS Group 800	59
	NFIRS Group 900	60





er	vice Area Performance	61
	Incidents & Streets by Drive Time - TRA	62
	Incidents - TRA	63
	Response Times - TRA	64
	Response Times by Year - TRA	65
	Turnout Times by Years -TRA	66
	ERF - TRA	67
	Incidents & Streets by Drive Time - AoR 21	68
	Incidents - AoR 21	69
	Response Times - AoR 21	70
	Response Times by Year - AoR 21	71
	Turnout Times by Years - AoR 21	72
	ERF - AoR 21	73
	Incidents & Streets by Drive Time - AoR 22	74
	Incidents - AoR 22	75
	Response Times - AoR 22	76
	Response Times by Year - AoR 22	77
	Turnout Times by Years - AoR 22	78
	ERF - AoR 22	79
	Incidents & Streets by Drive Time - AoR 23	80
	Incidents - AoR 23	81
	Response Times - AoR 23	82
	Response Times by Year - AoR 23	83
	Turnout Times by Years - AoR 23	84
	ERF - AoR 23	85
	Incidents & Streets by Drive Time - AoR 24	86
	Incidents - AoR 24	87
	Response Times - AoR 24	88
	Response Times by Year - AoR 24	89
	Turnout Times by Years - AoR 24	90
	ERF - AoR 24	91





ideal Stations	92
4 Stations	93
4 Stations - 4 min and 8 min Drive Times Co	mparison 94
4 Stations - 4 Minute Catchment Incidents	95
4 Stations - Growth: In Progress	96
4 Stations - Growth: High Likelihood	97
4 Stations - Growth: Low Likelihood	98
Station 21 to 411 W Higgins	99
Station 22 to Identified Alternate Location S	Site 100
Station 22 to Ideal Identified Location Area	101
Station 21 and Station 22 Moved - 4 min an Times Comparison	d 8 min Drive 102
Station 21 and Station 22 Moved - 4 Minute Incidents	: Catchment 103
Station 21 and Station 22 Moved - 4 Minute Incidents with Growth	: Catchment 104
Auto Aid Impact	105
Selected Auto Aid Stations	106
Barrington Countryside FPD Station 37	107
Barrington Countryside FPD Station 39	108
East Dundee and Countryside FPD Station 4	1 109
Elgin FD Station 1	110
Elgin FD Station 2	111
Elk Grove Village FD Station 10	112
Hanover Park FD Station 15	113
Inverness FPD Station 36	114
Palatine FD Station 84	115
Rolling Meadows FD Station 16	116
Schaumburg FD Station 51	117
Schaumburg FD Station 52	118
Schaumburg FD Station 53	119
Schaumburg FD Station 54	120
Schaumburg FD Station 55	121
Streamwood FD Station 31	122





## **Auto Aid Impact**

Streamwood FD Station 32	123
Streamwood FD Station 33	124
West Dundee FD Station 31	125





**Definitions** 





All Incidents: All incidents regardless of NFIRS group codes.

**AOR:** Area of Responsibility. The geographical area in which a particular fire station has primary responsibility to respond.

**AW:** Area workload is the percentage of a given time frame in which there is a demand for service within a station's AoR.

**Catchment:** The area covered by drive time from the fire station and is displayed by minute intervals. This is calculated based on speed limits along the most direct route to the scene from the fire station.

**Coverage:** A geographical area within which a fire station(s) provides services.

**Drive Time:** The time measured from fire company going en-route to fire company arriving on scene.

**EMS Incidents:** Incidents in the NFIRS group codes 300's. These also include rescues that may or may not have medical components.

**ERF:** The acronym for Effective Response Force which is the minimum number of personnel and equipment needed to effectively mitigate an incident.

Fire Incidents: Incidents in the NFIRS group codes 100's.

Historical: Incidents that have happened in the past. Data that has been collected in the past.

*Hotspot:* A representation of an area with a statistical higher density than its surrounding area.

Other Incidents: Incidents in the NFIRS group codes 200's, and 400's through 900's.

**Projected:** The results that may happen in the future based on analysis.

**Response Time:** The time measured from fire company notification to fire company on scene. This consists of Turnout Time and Drive Time.

**Service Area:** A geographical area where service is provided or demanded.

**STAC:** The acronym for Station Concentration and is the count of fire stations within an eightminute travel time from an incident.

**TRA:** The complete geographical area in which a fire agency is responsible to provide service.

*Turnout Time:* The time measured from fire company notification to fire company going en-route.





Demographic Overview

Demographic - TRA

Demographic - AoR 21

Demographic - AoR 22

Demographic - AoR 23

Demographic - AoR 24






The following demographic data is provided using Esri's demographic estimates for popular variables including: 2021 Total Population, 2021 Household Population, 2021 Median Age, 2021 Median Household Income, 2021 Per Capita Income, 2021 Diversity index and many more. Data is available from country, state, county, ZIP Code, tract, and block group level.

					\$
	TOTAL POPULATION	TOTAL HOUSEHOLDS	> 65 YEARS OF AGE	< 5 YEARS OF AGE	MEDIAN INCOME
TRA	52,462	18,520	8,059	2,947	\$103,004
AoR 21	17,473	6,047	2,558	1,001	\$91,297
AoR 22	16,459	6,117	2,605	987	\$82,843
AoR 23	13,474	4,618	2,265	591	\$145,456
AoR 24	5,057	1,738	631	367	\$120,422











































































































Service Area Overview Area Served by Drive Times - TRA 4 min and 8 min Drive Times - TRA Streets Covered by Drive Times - TRA Area Served by Drive Times - AoR 21 4 min and 8 min Drive Times - AoR 21 Streets Covered by Drive Times - AoR 21 TRA Coverage - AoR 21 Area Served by Drive Times - AoR 22 4 min and 8 min Drive Times - AoR 22 Streets Covered by Drive Times - AoR 22 TRA Coverage - AoR 22 Area Served by Drive Times - AoR 23 4 min and 8 min Drive Times - AoR 23 Streets Covered by Drive Times - AoR 23 TRA Coverage - AoR 23 Area Served by Drive Times - AoR 24 4 min and 8 min Drive Times - AoR 24 Streets Covered by Drive Times - AoR 24 TRA Coverage - AoR 24






		Ö		Ö
	AREA SERVED	4 MIN CATCHMENT AREA	STREETS SERVED	4 MIN CATCHMENT STREETS
TRA	22.6	50%	266.4	71%
AoR 21	3.7	64%	63.6	74%
AoR 22	9.8	40%	82.4	67%
AoR 23	3	<b>73</b> %	51.2	<b>77</b> %
AoR 24	6.1	42%	69.3	54%


















8 MINUTE COVERAGE

**11.2** 

**50%** 

AREA IN SQUARE MILES

92%

AREA IN SQUARE MILES


PERCENTAGE OF TRA

PERCENTAGE OF TRA




















Street travel time is the time of travel from the fire stations and is displayed in one-minute increments.
















64%

92%

AREA IN SQUARE MILES PERCENTAGE OF AOR 21 AREA IN SQUARE MILES PERCENTAGE OF AOR 21

















Street travel time is the time of travel from the fire stations and is displayed in one-minute increments.









0

8 MINUTE COVERAGE

2.5

**11%** 

**7.4** 

33%

AREA IN SQUARE MILES PERCENTAGE OF TRA


**AREA IN SQUARE MILES** 

PERCENTAGE OF TRA


























8 MINUTE COVERAGE

40%


83%

AREA IN SQUARE MILES PERCENTAGE OF AOR 22 AREA IN SQUARE MILES PERCENTAGE OF AOR 22




















Street travel time is the time of travel from the fire stations and is displayed in one-minute increments.









4.3

19%

AREA IN SQUARE MILES PERCENTAGE OF TRA



8 MINUTE COVERAGE

14.6


**65%** 

**AREA IN SQUARE MILES** 

PERCENTAGE OF TRA



















**73%** 

97%

AREA IN SQUARE MILES PERCENTAGE OF AOR 23 AREA IN SQUARE MILES PERCENTAGE OF AOR 23
















Street travel time is the time of travel from the fire stations and is displayed in one-minute increments.









(

**8** MINUTE COVERAGE

2.2

10%

3.5

**15%** 

AREA IN SQUARE MILES PERCENTAGE OF TRA


**AREA IN SQUARE MILES** 

PERCENTAGE OF TRA


























8 MINUTE COVERAGE

2.6

**42%** 


98%

AREA IN SQUARE MILES PERCENTAGE OF AOR 24 AREA IN SQUARE MILES PERCENTAGE OF AOR 24




















Street travel time is the time of travel from the fire stations and is displayed in one-minute increments.









2.6

**4** MINUTE COVERAGE

**12**%

6 9.

42%

AREA IN SQUARE MILES PERCENTAGE OF TRA

**AREA IN SQUARE MILES** 

PERCENTAGE OF TRA



Catchments represent the area covered by drive time from the fire stations and are displayed in one-minute increments.

**8** MINUTE COVERAGE



# **All Incidents**

**Inside TRA Incidents** 

**Outside TRA Incidents** 

NFIRS Group - 100

NFIRS Group - 200

NFIRS Group - 300

NFIRS Group - 400

NFIRS Group - 500

NFIRS Group - 600


NFIRS Group - 700

NFIRS Group - 800

NFIRS Group - 900









# HOFFMAN ESTATES FIRE DEPARTMENT

**SOURCE OF INCIDENT DATA** 



20,700 TOTAL INCIDENTS

**19,104** TRA INCIDENTS



**JAN 2019 - JUN 2022** 

**INCIDENT TIME PERIOD** 


1,596
OUTSIDE TRA INCIDENTS





Incident Classes:
Fire: All NFIRS group 100
EMS: All NFIRS group 300
Other: All NFIRS groups excluding groups 100 and 300






		2019	2020	2021	2022
Д	All Incidents	5,421	5,061	5,835	2,787
	Fire	77	65	77	37
**	EMS	4,074	3,828	4,490	2,129
lack	Other	1,270	1,168	1,268	621









Fire 358 Incidents

Brush or brush-and-grass mixture fire	9
Building fire	67
Building Fire Out of town	55
Chimney or flue fire, confined to chimney or flue	1
Cooking fire, confined to container	58
Dumpster or other outside trash receptacle fire	16
Fire contained in Appliance	2
Fire, other	4
Fires in structure other than in a building	2
Forest, woods or wildland fire	1
Fuel burner/boiler malfunction, fire confined	2
Grass fire	4
Mulch Fire	32
Natural vegetation fire, other	3
Off-road vehicle or heavy equipment fire	1
Outside equipment fire	3
Outside rubbish fire, other	5
Outside rubbish, trash or waste fire	21
Passenger vehicle fire	53
Road freight or transport vehicle fire	9
Special outside fire, other	1
Trash or rubbish fire, contained	9





# **Overpressure Rupture Explosion Overheat No Fire**

## 23 Incidents

Air or gas rupture of pressure or process vessel	1
Excessive heat, scorch burns with no ignition	19
Fireworks explosion (no fire)	1
Overpressure rupture of air or gas pipe/pipeline	1
Overpressure rupture of steam boiler	1





Rescue EMS 15,256 Incidents

Accident involving bicycle	13
Cardiac Emergency	3
Check on Well Being - No Patient	11
Chemical abuse, drugs or alcohol	3
Emergency medical service incident, other	8
EMS call, excluding vehicle accident with injury	13,891
Ems Call, No Patient Contact	38
Extrication of victim(s) from vehicle	6
Extrication, rescue, other	3
Fall injury	3
High-angle rescue	2
Lock-in (if lock out , use 511 )	11
Medical Alert-False Activation	60
Medical assist, assist EMS crew	9
Motor vehicle accident with extrication	42
Motor vehicle accident with injuries	879
Motor vehicle accident with no injuries.	79
Motor vehicle/pedestrian accident (MV Ped)	23
OB emergency, childbirth	1
Psychological emergency	1
Removal of victim(s) from stalled elevator	155
Rescue or EMS standby	1
Search for person in water	1
Swift water rescue	1
Swimming/recreational water areas rescue	1
Trauma not related to a motor vehicle accident	1
Vehicle Accident involving motorcycle	7
Water & ice-related rescue, other	2
Watercraft rescue	1





## **Hazardous Condition No Fire**

## **505 Incidents**

Accident, potential accident, other	1
Arcing, shorted electrical equipment	31
Attempted burning, illegal action, other	1
Biological hazard, confirmed or suspected	4
Breakdown of light ballast	2
Building or structure weakened or collapsed	4
Carbon monoxide incident	91
Chemical hazard (no spill or leak)	3
Chemical spill or leak	6
Combustible/flammable gas/liquid condition, other	3
Electrical wiring/equipment problem, other	32
Gas leak (natural gas or LPG)	188
Gasoline or other flammable liquid spill	11
Hazardous condition, other	2
Heat from short circuit (wiring), defective/worn	7
Oil or other combustible liquid spill	2
Overheated motor	33
Power line down	80
Toxic condition, other	1
Vehicle accident, general cleanup	3





Service Call 1,182 Incidents

Animal problem	2
Animal rescue	4
Assist invalid	358
Assist police or other governmental agency	64
Cover assignment, standby, moveup	34
Defective elevator, no occupants	23
Elevator, Open line - no occupants	7
Lock-out	120
Odor Investigation Unfounded/Unknown (if odor	195
Person in distress, other	8
Police matter	106
Public service	52
Public service assistance, other	75
Ring or jewelry removal	3
Service Call, other	3
Smoke Detector Install	4
Smoke or odor removal	31
Unauthorized burning	4
Water evacuation	4
Water or steam leak	62
Water problem, other	23





## **Canceled Good Intent**

# 1,132 Incidents

Allowable use of outdoor fireplace	4
Authorized controlled burning	15
Dispatched & canceled en route	624
Dispatched & returned by another agency	86
EMS call, party transported by non-fire agency	5
Errant Dispatch/Dispatcher Error	14
Good intent call, No Patient Contact	35
Good intent call, other	50
HazMat release investigation w/no HazMat	10
No incident found on arrival at dispatch address	176
Prescribed fire	2
Smoke from barbecue, tar kettle	3
Smoke scare, odor of smoke	56
Steam, other gas mistaken for smoke, other	15
Steam, vapor, fog or dust thought to be smoke	14
Vicinity alarm (incident in other location)	2
Wires down, Not power	17
Wrong location	4





### **False Alarm False Call** 2.216 Incidents Alarm system activation, no fire - unintentional 335 Alarm system sounded due to malfunction 172 Bomb scare - no bomb 2 Broken sprinkler due to being struck 4 Broken sprinkler due to freezing Broken Sprinkler Pipe - Unknown Reason 4 Carbon monoxide detector activation, no CO 125 Central station, malicious false alarm 19 CO detector - Low Battery/End of Life 8 CO detector activation due to malfunction 42 Detector activation, no fire - unintentional 111 Direct tie to FD, malicious false alarm 30 22 Dry valve tripped - no fire **Emergency Medical Alarm-False activation** 8 2 Extinguishing system activation Extinguishing system activation due to malfunction 4 False alarm or false call, other 8 Heat detector activation due to malfunction 26 Malicious, mischievous false call, other 38 Municipal alarm system, malicious false alarm 12 Open 911 Line Ambulance Response 4 Smoke Alarm - Low Battery/End of Life 8 Smoke detector activation due to malfunction 264 Smoke detector activation, no fire - unintentional 467 Sprinkler activation due to malfunction 24 Sprinkler activation, no fire - unintentional 22 6 Supervisory (tamper, low temp, low pressure) System malfunction, other 84 Trouble Alarm - Loss of signal/Comm Failure 22 Trouble Alarm - Phone line problem 1 Trouble Alarm - Radio transmitter problem 16 Trouble Alarm - unknown reason 33 Trouble Alarm Reset 28 Trouble Alarm Unable to reset 170 Trouble alarm due to power outage 29

Unintentional transmission of alarm, other



57



## **Severe Weather and Natural Disaster**

## **3** Incidents

Flood assessment	1
Lightning strike (no fire)	2





# **Special Incident Type**

## **7** Incidents

Citizen complaint	5
Special type of incident, other	2





TRA

AoR 21

AoR 22

AoR 23


AoR 24











# **NFIRS Groups: Counts and Percentages**

100	200	300	400	500	600	700	800	900
1.3%	0.1%	76.1%	2.5%	5.8%	3%	11.2%	<0.1%	<0.1%
256	22	14,521	478	1,100	568	2,135	3	7














100	200	300	400	500	600	700	800	900
1.6%	0.1%	72.9%	3.7%	5.9%	2.9%	12.9%	<0.1%	0.1%
87	4	3,981	201	322	159	703	2	3














100	200	300	400	500	600	700	800	900
1%	0.1%	79.2%	1.8%	5.1%	2.5%	10.2%	0%	<0.1%
90	12	7,451	170	479	238	963	0	3














100	200	300	400	500	600	700	800	900
1.6%	0.1%	75.5%	2.5%	8.9%	2.7%	8.6%	<0.1%	0%
35	2	1,620	53	191	58	185	1	0














100	200	300	400	500	600	700	800	900
2.1%	0.2%	70.7%	2.6%	5.2%	5.4%	13.7%	0%	<0.1%
44	4	1,469	54	108	113	284	0	1





NFIRS Group 100 - 900

NFIRS Group 100

NFIRS Group 200

NFIRS Group 300

NFIRS Group 400

NFIRS Group 500

NFIRS Group 600

NFIRS Group 700

NFIRS Group 800


NFIRS Group 900











NFIRS 100 - 900 : All Incidents
Percentage of TRA incidents



**29%** 

49%



11%



11%

AOR **21** 

AOR **22** 


AOR **24** 











NFIRS 100: Fire

**Percentage of TRA incidents** 



**34**%

**35%** 



14%



**17%** 

AOR **21** 

AOR **22** 

AOR **23** 








22 INCIDENTS





NFIRS 200 : Overpressure Rupture Explosion Overheat No Fire Percentage of TRA incidents



**18%** 



**55%** 



9%



**18%** 

AOR **21** 

AOR **22** 


**AOR 24** 











NFIRS 300: Rescue EMS

**Percentage of TRA incidents** 





**51%** 



11%



AOR **22** 


AOR **23** 











**NFIRS 400: Hazardous Condition No Fire** 

**Percentage of TRA incidents** 





36%



11%



AOR **22** 


AOR **24** 











NFIRS 500 : Service Call Percentage of TRA incidents



**29%** 

44%



**17%** 



10%

AOR **21** 

**AOR 22** 


AOR **24** 











NFIRS 600 : Canceled Good Intent Percentage of TRA incidents



28%

**42%** 



10%



20%

AOR **21** 

AOR **22** 


AOR **23** 











NFIRS 700 : False Alarm False Call Percentage of TRA incidents



33%

**45%** 



9%



**13%** 

AOR **21** 

AOR **22** 

AOR **23** 








**INCIDENTS** 





**NFIRS 800: Severe Weather and Natural Disaster Percentage of TRA incidents** 



**67%** 







AOR **21** 

AOR **22** 














NFIRS 900 : Special Incident Type Percentage of TRA incidents



43%

43%



0%



14%

AOR **21** 

AOR **22** 

AOR **23** 





Incidents & Streets by Drive Time - TRA
Incidents - TRA

**Response Times - TRA** 

Response Times by Year - TRA

Turnout Times by Years -TRA

**ERF-TRA** 

Incidents & Streets by Drive Time - AoR 21

Incidents - AoR 21

Response Times - AoR 21

Response Times by Year - AoR 21

Turnout Times by Years - AoR 21

ERF - AoR 21

Incidents & Streets by Drive Time - AoR 22

Incidents - AoR 22

Response Times - AoR 22

Response Times by Year - AoR 22

Turnout Times by Years - AoR 22

ERF - AoR 22

Incidents & Streets by Drive Time - AoR 23

Incidents - AoR 23

Response Times - AoR 23

Response Times by Year - AoR 23

Turnout Times by Years - AoR 23

ERF - AoR 23

Incidents & Streets by Drive Time - AoR 24

Incidents - AoR 24

Response Times - AoR 24

Response Times by Year - AoR 24


Turnout Times by Years - AoR 24

ERF - AoR 24












Incidents and streets are displayed in one-minute increments based on travel time from the closest fire station.













Percentages of "First On Scene" from Historic RESPONSE Times

WITHIN 4 MIN CATCHMENT

**¾** 74%

FIRE INCIDENTS

82% EMS INCIDENTS

63% FIRE INCIDENTS

73% EMS INCIDENTS



WITHIN COMPLETE TRA



# Response Time (h:mm:ss)

	90%	80%	70%	60%	50%
All	00:06:34	00:05:39	00:05:05	00:04:38	00:04:15
Fire	00:07:22	00:06:28	00:05:42	00:05:12	00:04:48
EMS	00:06:13	00:05:24	00:04:53	00:04:26	00:04:04



# All Incidents Response Time (h:mm:ss)

	90%	80%	<b>70</b> %	60%	50%
Historic	00:06:34	00:05:39	00:05:05	00:04:38	00:04:15
Calculated	00:05:43	00:04:50	00:04:12	00:03:47	00:03:27



# Fire Incidents Response Time (h:mm:ss)

	90%	80%	70%	60%	50%
Historic	00:07:22	00:06:28	00:05:42	00:05:12	00:04:48
Calculated	00:06:14	00:05:27	00:04:51	00:04:22	00:04:07



# **EMS Incidents Response Time (h:mm:ss)**

	90%	80%	70%	60%	50%
Historic	00:06:13	00:05:24	00:04:53	00:04:26	00:04:04
Calculated	00:05:41	00:04:48	00:04:08	00:03:44	00:03:20



# Other Incidents Response Time (h:mm:ss)

	90%	80%	<b>70</b> %	60%	50%
Historic	00:07:23	00:06:24	00:05:46	00:05:16	00:04:50
Calculated	00:05:44	00:04:58	00:04:21	00:03:53	00:03:41





Ö	, <u>,</u>	All Incidents Res	ponse Time (h:	mm:ss)	
er	90%	80%	70%	60%	50%
2019	00:06:42	00:05:40	00:05:07	00:04:21	00:04:33
2020	00:06:29	00:05:35	00:05:01	00:04:24	00:04:11
2021	00:06:55	00:05:51	00:05:12	00:04:42	00:04:17
2022	00:06:48	00:05:45	00:05:07	00:04:39	00:04:13
Ö	Fi	re Incidents Re	sponse Time (h	:mm:ss)	
	90%	80%	70%	60%	50%
2019	00:09:33	00:07:30	00:06:18	00:05:29	00:05:07
2020	00:10:27	00:07:39	00:06:26	00:05:38	00:05:10
2021	00:11:46	00:08:16	00:06:58	00:06:13	00:05:44
2022	00:13:34	00:09:00	00:06:59	00:06:05	00:05:04
Ō	Eſ	VIS Incidents Re	sponse Time (h	:mm:ss)	
	90%	80%	70%	60%	50%
2019	00:04:43	00:04:18	00:09:37	00:03:49	00:06:12
2020	00:04:53	00:04:26	00:04:04	00:03:41	00:03:31
2021	00:04:41	00:06:56	00:04:17	00:04:04	00:05:27
2022	00:06:24	00:05:31	00:04:57	00:04:31	00:04:07
<b>O</b>	Ot	her Incidents Ro	esponse Time (I	n:mm:ss)	
	90%	80%	70%	60%	50%
2019	00:07:20	00:06:15	00:05:36	00:05:06	00:04:41
2020	00:07:21	00:06:12	00:05:31	00:05:01	00:04:36
2021	00:07:45	00:06:24	00:05:43	00:05:07	00:04:37



2022

00:07:27

00:06:21

00:05:37

00:05:02

00:04:36



O		All Incidents Tu	rnout Time (h:n	nm:ss)	
CI.	90%	80%	70%	60%	50%
2019	00:01:56	00:01:35	00:01:18	00:00:56	00:00:58
2020	00:02:07	00:01:47	00:01:37	00:01:16	00:01:26
2021	00:02:09	00:01:44	00:01:30	00:01:18	00:01:10
2022	00:01:55	00:01:38	00:01:24	00:01:12	00:01:02
Ö		ire Incidents Tu	ırnout Time (h:ı	mm:ss)	
	90%	80%	70%	60%	50%
2019	00:02:06	00:01:53	00:01:41	00:01:31	00:01:23
2020	00:03:04	00:02:05	00:01:51	00:01:41	00:01:33
2021	00:03:26	00:02:26	00:02:04	00:01:46	00:01:28
2022	00:03:50	00:01:48	00:01:43	00:01:26	00:01:23
Ö	E	MS Incidents Tu	ırnout Time (h:	mm:ss)	
	90%	80%	70%	60%	50%
2019	00:01:08	00:03:26	00:02:10	00:00:46	00:00:39
2020	00:01:30	00:01:19	00:01:10	00:01:02	00:02:33
2021	00:01:16	00:01:11	00:01:57	00:01:01	00:00:57
2022	00:01:50	00:01:32	00:01:18	00:01:07	00:00:59
Ö	0	ther Incidents T	urnout Time (h	:mm:ss)	
	90%	80%	70%	60%	50%
2019	00:02:06	00:01:44	00:01:29	00:01:14	00:00:55
2020	00:02:17	00:01:57	00:01:44	00:01:34	00:01:26
2021	00:02:12	00:01:50	00:01:37	00:01:29	00:01:19



2022

00:02:06

00:01:48

00:01:38

00:01:25


00:01:15





# **EFFECTIVE RESPONSE FORCE**FULL COMPLIMENT WITHIN 8 MINUTES







63%

OF INCIDENTS ARE COVERED BY  ${f 2}$  STATIONS

**15%** 


OF INCIDENTS ARE COVERED BY **3** STATIONS

0%

OF INCIDENTS ARE COVERED BY **4** STATIONS


















Percentages of "First On Scene" from Historic RESPONSE Times

WITHIN 4 MIN CATCHMENT

73% FIRE INCIDENTS

82% EMS INCIDENTS

69%

73%

**FIRE INCIDENTS** 





WITHIN COMPLETE AOR



# Response Time (h:mm:ss)

	90%	80%	70%	60%	50%
All	00:06:21	00:05:31	00:05:02	00:04:40	00:04:20
Fire	00:06:48	00:05:50	00:05:24	00:05:02	00:04:42
EMS	00:06:03	00:05:21	00:04:53	00:04:30	00:04:12



## All Incidents Response Time (h:mm:ss)

	90%	80%	70%	60%	50%
Historic	00:06:21	00:05:31	00:05:02	00:04:40	00:04:20
Calculated	00:05:23	00:04:46	00:04:12	00:03:50	00:03:34



# Fire Incidents Response Time (h:mm:ss)

	90%	80%	70%	60%	50%
Historic	00:06:48	00:05:50	00:05:24	00:05:02	00:04:42
Calculated	00:05:22	00:04:46	00:04:12	00:04:07	00:03:53



# **EMS Incidents Response Time (h:mm:ss)**

	90%	80%	70%	60%	50%
Historic	00:06:03	00:05:21	00:04:53	00:04:30	00:04:12
Calculated	00:05:27	00:04:52	00:04:20	00:03:52	00:03:34



# Other Incidents Response Time (h:mm:ss)

	90%	80%	<b>70</b> %	60%	50%
Historic	00:07:15	00:06:05	00:05:25	00:05:02	00:04:42
Calculated	00:05:18	00:04:21	00:03:55	00:03:47	00:03:33





Ö	. <u>A</u>	All Incidents Res	ponse Time (h:	mm:ss)	
ti de la composición dela composición de la composición de la composición de la composición dela composición dela composición dela composición de la composición de la composición dela composición de la composición dela	90%	80%	70%	60%	50%
2019	00:06:24	00:05:33	00:05:03	00:04:41	00:04:18
2020	00:06:07	00:05:26	00:05:00	00:04:38	00:04:19
2021	00:06:30	00:05:32	00:05:00	00:04:38	00:04:19
2022	00:06:13	00:05:28	00:05:01	00:04:39	00:04:18
Ö	Fi	re Incidents Re	sponse Time (h	:mm:ss)	
	90%	80%	70%	60%	50%
2019	00:05:53	00:05:32	00:05:11	00:05:07	00:04:48
2020	00:05:38	00:05:25	00:05:13	00:04:48	00:04:41
2021	00:07:54	00:06:05	00:05:35	00:04:53	00:04:36
2022	00:06:45	00:05:24	00:05:04	00:04:42	00:04:33
Ö			"	,	
		VIS Incidents Re		•	
	90%	80%	70%	60%	50%
2019	00:06:07	00:05:23	00:04:53	00:04:29	00:04:08
2020	00:05:51	00:05:19	00:04:53	00:04:28	00:04:11
2021	00:06:17	00:05:24	00:04:54	00:04:33	00:04:14
2022	00:06:01	00:05:19	00:04:53	00:04:32	00:04:13
ÖA	Ot	her Incidents Re	esponse Time (I	n:mm:ss)	
	90%	80%	70%	60%	50%
2019	00:07:08	00:06:11	00:05:32	00:05:06	00:04:46
2020	00:07:21	00:06:04	00:05:20	00:04:58	00:04:41
2021	00:07:00	00:05:50	00:05:15	00:04:52	00:04:34



2022

00:07:03

00:05:54

00:05:24

00:04:51

00:04:32



Ö		All Incidents Tui	rnout Time (h:n	nm:ss)	
	90%	80%	70%	60%	50%
2019	00:01:52	00:01:31	00:01:17	00:01:01	00:00:49
2020	00:02:04	00:01:44	00:01:33	00:01:22	00:01:13
2021	00:02:03	00:01:40	00:01:27	00:01:16	00:01:06
2022	00:02:00	00:01:39	00:01:24	00:01:13	00:01:02
<b>~</b> 4					
G	F	ire Incidents Tu	rnout Time (h:	mm:ss)	
_	90%	80%	70%	60%	50%
2019	00:01:52	00:01:48	00:01:39	00:01:31	00:01:18
2020	00:02:30	00:01:59	00:01:50	00:01:37	00:01:36
2021	00:03:40	00:01:49	00:01:41	00:01:26	00:01:12
2022	00:02:09	00:02:02	00:01:44	00:01:31	00:01:23
Č.					
GIR	E	MS Incidents Tu	ırnout Time (h:	mm:ss)	
	90%	80%	70%	60%	50%
2019	00:01:45	00:01:26	00:01:11	00:00:57	00:00:46
2020	00:01:57	00:01:38	00:01:27	00:01:16	00:01:07
2021	00:02:04	00:01:38	00:01:24	00:01:14	00:01:03
2022	00:01:52	00:01:32	00:01:19	00:01:08	00:00:59
<b>~</b>					
	Ot	ther Incidents T	urnout Time (h	:mm:ss)	
	90%	80%	70%	60%	50%
2019	00:02:05	00:01:42	00:01:28	00:01:15	00:00:58
2020	00:02:17	00:01:55	00:01:44	00:01:37	00:01:27
2021	00:01:59	00:01:42	00:01:33	00:01:25	00:01:16
2022	00:02:10	00:01:47	00:01:36	00:01:24	00:01:13








# **EFFECTIVE RESPONSE FORCE**FULL COMPLIMENT WITHIN 8 MINUTES







93%

of incidents are covered by  ${f 2}$  stations

1%
OF INCIDENTS ARE

OF INCIDENTS ARE COVERED BY **3** STATIONS


0%

OF INCIDENTS ARE COVERED BY **4** STATIONS












Incidents and streets are displayed in one-minute increments based on travel time from the closest fire station.













Percentages of "First On Scene" from Historic RESPONSE Times

WITHIN 4 MIN CATCHMENT

75% FIRE INCIDENTS



66% FIRE INCIDENTS

78% TRIS



WITHIN COMPLETE AOR



# Response Time (h:mm:ss)

	90%	80%	70%	60%	50%
All	00:06:13	00:05:21	00:04:47	00:04:20	00:03:55
Fire	00:06:41	00:06:05	00:05:32	00:05:00	00:04:42
EMS	00:05:53	00:05:05	00:04:32	00:04:06	00:03:42



## All Incidents Response Time (h:mm:ss)

	90%	80%	70%	60%	50%
Historic	00:06:13	00:05:21	00:04:47	00:04:20	00:03:55
Calculated	00:05:06	00:04:12	00:03:44	00:03:20	00:03:18



### Fire Incidents Response Time (h:mm:ss)

	90%	80%	70%	60%	50%
Historic	00:06:41	00:06:05	00:05:32	00:05:00	00:04:42
Calculated	00:05:47	00:05:18	00:04:41	00:04:19	00:04:08



# **EMS Incidents Response Time (h:mm:ss)**

	90%	80%	70%	60%	50%
Historic	00:05:53	00:05:05	00:04:32	00:04:06	00:03:42
Calculated	00:04:57	00:04:05	00:03:41	00:03:18	00:03:08



# Other Incidents Response Time (h:mm:ss)

	90%	80%	70%	60%	50%
Historic	00:07:05	00:06:12	00:05:37	00:05:10	00:04:43
Calculated	00:05:33	00:04:44	00:04:02	00:03:44	00:03:30





Ö	,	III Incidents Pos	ponse Time (h:	mm:ss)	
U.	90%	80%	70%	60%	50%
2019	00:06:16	00:05:26	00:04:51	00:04:23	00:04:00
2020	00:06:02	00:05:13	00:04:41	00:04:13	00:03:49
2021	00:06:25	00:05:27	00:04:49	00:04:22	00:03:55
2022	00:06:05	00:05:13	00:04:40	00:04:13	00:03:50
Ö	Fi	re Incidents Re	sponse Time (h	:mm:ss)	
	90%	80%	70%	60%	50%
2019	00:07:00	00:05:57	00:05:31	00:05:01	00:04:45
2020	00:06:26	00:05:47	00:05:41	00:05:10	00:04:46
2021	00:06:34	00:06:13	00:04:45	00:04:37	00:04:25
2022	00:06:31	00:05:31	00:05:00	00:04:42	00:04:28
Ö	Eſ	VIS Incidents Re	sponse Time (h	:mm:ss)	
-	90%	80%	70%	60%	50%
2019	00:05:52	00:05:07	00:04:35	00:04:09	00:03:47
2020	00:05:50	00:05:02	00:04:27	00:04:00	00:03:36
2021	00:06:04	00:05:07	00:04:36	00:04:08	00:03:44
2022	00:05:45	00:05:03	00:04:28	00:04:04	00:03:40
Ö	Ot	her Incidents R	esponse Time (I	n:mm:ss)	
	90%	80%	70%	60%	50%
2019	00:06:56	00:06:11	00:05:38	00:05:14	00:04:48
2020	00:06:43	00:05:54	00:05:21	00:04:52	00:04:32
2021	00:07:19	00:06:24	00:05:45	00:05:17	00:04:46



2022

00:06:50

00:05:57

00:05:24

00:04:48

00:04:28



Ö		All Incidents Tui	rnout Time (h:n	nm:ss)	
c	90%	80%	70%	60%	50%
2019	00:01:58	00:01:35	00:01:19	00:01:04	00:00:52
2020	00:02:07	00:01:47	00:01:33	00:01:22	00:01:13
2021	00:02:08	00:01:43	00:01:31	00:01:19	00:01:08
2022	00:01:52	00:01:35	00:01:21	00:01:10	00:01:01
<b>~</b> 4					
G	F	ire Incidents Tu	rnout Time (h:r	mm:ss)	
_	90%	80%	70%	60%	50%
2019	00:02:06	00:01:57	00:01:51	00:01:35	00:01:22
2020	00:02:15	00:01:58	00:01:55	00:01:41	00:01:32
2021	00:02:26	00:02:18	00:01:56	00:01:52	00:01:32
2022	00:01:48	00:01:46	00:01:43	00:01:29	00:01:25
Č.					
GIR	E	MS Incidents Tu	irnout Time (h:	mm:ss)	
	90%	80%	70%	60%	50%
2019	00:01:54	00:01:31	00:01:13	00:01:00	00:00:51
2020	00:02:03	00:01:42	00:01:29	00:01:18	00:01:09
2021	00:02:06	00:01:40	00:01:26	00:01:14	00:01:03
2022	00:01:49	00:01:30	00:01:15	00:01:06	00:00:58
<b>~</b>					
	Ot	ther Incidents T	urnout Time (h	:mm:ss)	
	90%	80%	70%	60%	50%
2019	00:02:08	00:01:48	00:01:33	00:01:21	00:01:02
2020	00:02:10	00:01:57	00:01:44	00:01:34	00:01:28
2021	00:02:12	00:01:52	00:01:41	00:01:32	00:01:25
2022	00:02:00	00:01:45	00:01:38	00:01:24	00:01:13








# **EFFECTIVE RESPONSE FORCE**FULL COMPLIMENT WITHIN 8 MINUTES







65%

of incidents are covered by  ${f 2}$  stations

29%

OF INCIDENTS ARE COVERED BY **3** STATIONS


0%

OF INCIDENTS ARE COVERED BY **4** STATIONS











Incidents and streets are displayed in one-minute increments based on travel time from the closest fire station.








84%

OF INCIDENTS ARE IN THE **4** MINUTE CATCHMENT





Percentages of "First On Scene" from Historic RESPONSE Times

WITHIN 4 MIN CATCHMENT

90% FIRE INCIDENTS

82% EMS INCIDENTS

80%

72% EMS INCIDENTS



WITHIN COMPLETE AOR



# Response Time (h:mm:ss)

	90%	80%	70%	60%	50%
All	00:06:21	00:05:37	00:05:05	00:04:39	00:04:20
Fire	00:06:36	00:05:16	00:05:03	00:04:50	00:04:35
EMS	00:06:06	00:05:24	00:04:57	00:04:31	00:04:12



## All Incidents Response Time (h:mm:ss)

	90%	80%	70%	60%	50%
Historic	00:06:21	00:05:37	00:05:05	00:04:39	00:04:20
Calculated	00:05:42	00:04:47	00:04:21	00:04:04	00:03:46



### Fire Incidents Response Time (h:mm:ss)

	90%	80%	70%	60%	50%
Historic	00:06:36	00:05:16	00:05:03	00:04:50	00:04:35
Calculated	00:06:10	00:04:53	00:04:34	00:04:20	00:03:53



# **EMS Incidents Response Time (h:mm:ss)**

-	90%	80%	70%	60%	50%
Historic	00:06:06	00:05:24	00:04:57	00:04:31	00:04:12
Calculated	00:05:47	00:04:46	00:04:20	00:04:02	00:03:47



# Other Incidents Response Time (h:mm:ss)

	90%	80%	70%	60%	50%
Historic	00:07:20	00:06:17	00:05:40	00:05:11	00:04:44
Calculated	00:05:24	00:04:47	00:04:24	00:04:09	00:03:40





Č.			//	,	
	90%	All Incidents Res 80%	sponse Time (h: 70%	mm:ss) 60%	50%
2019	00:06:07	00:05:24	00:04:58	00:04:35	00:04:19
2020	00:06:11	00:05:25	00:04:59	00:04:38	00:04:17
2021	00:06:44	00:05:47	00:05:15	00:04:38	00:04:18
2022	00:06:31	00:05:54	00:05:11	00:04:50	00:04:28
Ö	Fi	re Incidents Re	sponse Time (h	:mm:ss)	
	90%	80%	70%	60%	50%
2019	00:05:03	00:04:53	00:04:52	00:04:41	00:04:02
2020	00:05:08	00:04:50	00:04:47	00:04:35	00:03:52
2021	00:06:36	00:05:57	00:05:32	00:05:15	00:05:12
2022	00:05:56	00:05:56	00:03:57	00:03:44	00:03:44
ŌŢ	Eſ	VIS Incidents Re	sponse Time (h	:mm:ss)	
-	90%	80%	70%	60%	50%
2019	00:05:52	00:05:15	00:04:53	00:04:32	00:04:16
2020	00:05:46	00:05:15	00:04:47	00:04:26	00:04:07
2021	00:06:18	00:05:35	00:05:05	00:04:31	00:04:15
2022	00:06:16	00:05:43	00:05:04	00:04:35	00:04:13
Ō	Ot	her Incidents Ro	esponse Time (I	h:mm:ss)	
	90%	80%	70%	60%	50%
2019	00:06:48	00:05:49	00:05:20	00:04:49	00:04:27
2020	00:07:23	00:06:21	00:05:33	00:05:09	00:04:45
2021	00:07:49	00:06:30	00:05:56	00:05:21	00:04:34



2022

00:06:46

00:06:17

00:06:03

00:05:38

00:05:11



.2.									
O		All Incidents Tu	rnout Time (h:n	nm:ss)					
	90%	80%	70%	60%	50%				
2019	00:01:48	00:01:29	00:01:16	00:01:00	00:00:49				
2020	00:01:59	00:01:45	00:01:30	00:01:21	00:01:13				
2021	00:01:59	00:01:36	00:01:23	00:01:12	00:01:04				
2022	00:01:49	00:01:36	00:01:24	00:01:10	00:01:04				
Ö		Fire Incidents Tu	ırnout Time (h:ı	mm:ss)					
	90%	80%	70%	60%	50%				
2019	00:01:58	00:01:53	00:01:37	00:01:31	00:01:28				
2020	00:05:45	00:01:42	00:01:36	00:01:33	00:01:29				
2021	00:03:13	00:03:03	00:02:25	00:02:13	00:01:34				
2022	00:01:44	00:01:44	00:01:28	00:01:25	00:01:25				
Ö		MS Incidents Tu	urnout Timo (h.	mm.cc)					
	90%	80%	70%	60%	50%				
2019	00:01:43	00:01:27	00:01:12	00:01:00	00:00:49				
2020	00:01:55	00:01:41	00:01:26	00:01:18	00:01:12				
2021	00:01:57	00:01:35	00:01:21	00:01:09	00:01:01				
2022	00:01:45	00:01:30	00:01:16	00:01:07	00:01:01				
Ö	0	th an Incidenta T	Summarut Times (In						
	Other Incidents Turnout Time (h:mm:ss)								
	90%	80%	70%	60%	50%				
2019	00:01:56	00:01:32	00:01:21	00:01:01	00:00:46				
2020	00:02:03	00:01:50	00:01:40	00:01:29	00:01:21				
2021	00:01:56	00:01:38	00:01:30	00:01:17	00:01:12				



2022

00:01:54

00:01:46

00:01:42

00:01:34

00:01:21






# **EFFECTIVE RESPONSE FORCE**

**FULL COMPLIMENT WITHIN 8 MINUTES** 





0%

OF INCIDENTS ARE

COVERED BY 3 STATIONS



0%

OF INCIDENTS ARE

COVERED BY 4 STATIONS

1 Station ERF 2 Stations ERF

3 Stations ERF


1%

OF INCIDENTS ARE

COVERED BY **2** STATIONS










Incidents and streets are displayed in one-minute increments based on travel time from the closest fire station.













Percentages of "First On Scene" from Historic RESPONSE Times

WITHIN 4 MIN CATCHMENT

**FIRE INCIDENTS** 



**FIRE INCIDENTS** 



WITHIN COMPLETE AOR



# Response Time (h:mm:ss)

	90%	80%	70%	60%	<b>50</b> %
All	00:07:56	00:06:58	00:06:22	00:05:53	00:05:28
Fire	00:09:08	00:07:54	00:07:30	00:06:47	00:06:29
EMS	00:07:29	00:06:40	00:06:04	00:05:38	00:05:14



## All Incidents Response Time (h:mm:ss)

	90%	80%	70%	60%	50%
Historic	00:07:56	00:06:58	00:06:22	00:05:53	00:05:28
Calculated	00:06:52	00:06:26	00:05:51	00:05:31	00:05:07



# Fire Incidents Response Time (h:mm:ss)

	90%	80%	70%	60%	50%
Historic	00:09:08	00:07:54	00:07:30	00:06:47	00:06:29
Calculated	00:07:46	00:06:34	00:06:22	00:05:51	00:05:33



## **EMS Incidents Response Time (h:mm:ss)**

	90%	80%	70%	60%	50%
Historic	00:07:29	00:06:40	00:06:04	00:05:38	00:05:14
Calculated	00:07:06	00:06:31	00:05:51	00:05:30	00:05:03



# Other Incidents Response Time (h:mm:ss)

	90%	80%	<b>70</b> %	60%	50%
Historic	00:08:55	00:07:33	00:06:54	00:06:26	00:06:02
Calculated	00:06:39	00:06:16	00:05:47	00:05:32	00:05:13





Ö	, <u> </u>	All Incidents Res	ponse Time (h:	mm:ss)		
ti de la composición dela composición de la composición de la composición de la composición dela composición dela composición dela composición de la composición de la composición dela composición de la composición dela	90%	80%	70%	60%	50%	
2019	00:07:54	00:06:53	00:06:13	00:05:42	00:05:18	
2020	00:07:34	00:06:45	00:06:19	00:05:49	00:05:18	
2021	00:07:56	00:07:00	00:06:24	00:05:58	00:05:34	
2022	00:08:13	00:07:01	00:06:25	00:05:54	00:05:29	
Ö	Fi	re Incidents Re	sponse Time (h	:mm:ss)		
	90%	80%	70%	60%	50%	
2019	00:07:54	00:07:30	00:06:57	00:06:20	00:06:06	
2020	00:07:54	00:07:39	00:06:28	00:05:57	00:05:05	
2021	00:08:20	00:08:13	00:08:02	00:07:36	00:06:47	
2022	00:09:38	00:09:38	00:07:22	00:06:29	00:06:29	
Ö	EMS Incidents Response Time (h:mm:ss)					
Ale				•	<b>50</b> 0/	
	90%	80%	70%	60%	50%	
2019	00:07:38	00:06:27	00:05:54	00:05:32	00:05:09	
2020	00:07:17	00:06:37	00:06:03	00:05:30	00:05:11	
2021	00:07:35	00:06:46	00:06:17	00:05:44	00:05:24	
2022	00:07:47	00:06:45	00:06:04	00:05:39	00:05:16	
Other Incidents Response Time (h:mm:ss)						
A				•	F00/	
	90%	80%	70%	60%	50%	
2019	00:09:08	00:07:32	00:06:49	00:06:27	00:05:55	
2020	00:08:16	00:07:21	00:06:33	00:06:09	00:05:45	
2021	00:09:27	00:07:16	00:06:44	00:06:15	00:05:58	



2022

00:08:46

00:07:56

00:07:05

00:06:48

00:05:58



Ö	All Incidents Turnout Time (h:mm:ss)				
-	90%	80%	70%	60%	50%
2019	00:02:07	00:01:43	00:01:24	00:01:07	00:00:54
2020	00:02:11	00:01:50	00:01:39	00:01:28	00:01:18
2021	00:02:14	00:01:52	00:01:38	00:01:24	00:01:12
2022	00:01:57	00:01:37	00:01:26	00:01:16	00:01:04
<b>.</b>					
9	F	ire Incidents Tu	rnout Time (h:r	mm:ss)	
_	90%	80%	70%	60%	50%
2019	00:02:17	00:01:58	00:01:31	00:01:25	00:01:24
2020	00:04:14	00:02:05	00:01:31	00:01:26	00:01:25
2021	00:02:48	00:02:13	00:01:28	00:01:20	00:01:19
2022	00:01:21	00:01:21	00:01:04	00:01:00	00:01:00
ر الأس					
	E	MS Incidents Tu	ırnout Time (h:	mm:ss)	
	90%	80%	70%	60%	50%
2019	00:02:08	00:01:42	00:01:23	00:01:06	00:00:55
2020	00:02:07	00:01:45	00:01:36	00:01:25	00:01:15
2021	00:02:12	00:01:48	00:01:36	00:01:21	00:01:11
2022	00:01:56	00:01:34	00:01:23	00:01:12	00:01:01
*					
	Other Incidents Turnout Time (h:mm:ss)				
	90%	80%	70%	60%	50%
2019	00:02:05	00:01:42	00:01:27	00:01:03	00:00:46
2020	00:02:19	00:02:01	00:01:44	00:01:33	00:01:24
2021	00:02:14	00:01:56	00:01:43	00:01:30	00:01:17
2022	00:01:58	00:01:44	00:01:36	00:01:23	00:01:13








# **EFFECTIVE RESPONSE FORCE**FULL COMPLIMENT WITHIN 8 MINUTES







38%

OF INCIDENTS ARE COVERED BY  ${f 2}$  STATIONS

2%

OF INCIDENTS ARE COVERED BY **3** STATIONS

0%

OF INCIDENTS ARE COVERED BY **4** STATIONS





#### 4 Stations

4 Stations - 4 min and 8 min Drive Times Comparison

4 Stations - 4 Minute Catchment Incidents

4 Stations - Growth: In Progress

4 Stations - Growth: High Likelihood

4 Stations - Growth: Low Likelihood

Station 21 to 411 W Higgins

Station 22 to Identified Alternate Station Location Site Station 22 to Ideal Identified Station Location Area

Station 22 to Ideal Identified Station Location Area


Station 21 and Station 22 Moved - 4 min and 8 min Drive Times Comparison

Station 21 and Station 22 Moved - 4 Minute Catchment Incidents

Station 21 and Station 22 Moved - 4 Minute Catchment Incidents with Growth












640 possible sites.





ERF

F 13%

OF INCIDENTS ARE COVERED BY  $oldsymbol{2}$  STATIONS

13%

OF INCIDENTS ARE COVERED BY **3** STATIONS

0%

OF INCIDENTS ARE COVERED BY **4** STATIONS


#### **Ideal Station Location:**


The Ideal Station Location was calculated using ESRI's Location - Allocation Analysis tool. 640 possible fire station sites were used with a 4 minute drive time as the cutoff to reach as many incidents as possible.















**4** MINUTE COVERAGE

AREA IN SQUARE MILES PERCENTAGE OF **TRA** 

Current 11.2 Ideal 13

50% 5**7**%



**8** MINUTE COVERAGE

**AREA IN SQUARE MILES** 

20.7

20.9

PERCENTAGE OF TRA

92%




Catchments represent the area covered by drive time from the fire stations and are displayed at the four-minute and eight-minute increments.











# WITHIN 4 MIN CATCHMENT

	Ö	Ö	
	FIRE INCIDENTS	EMS INCIDENTS	OTHER INCIDENTS
Current	<b>77%</b>	83%	80%
Ideal	80%	88%	84%












640 possible sites.



#### **Ideal Station Location:**

The Ideal Station Location was calculated using ESRI's Location - Allocation Analysis tool. 640 possible fire station sites were used with a 4 minute drive time as the cutoff to reach as many incidents as possible.












640 possible sites.





The Ideal Station Location was calculated using ESRI's Location - Allocation Analysis tool. 640 possible fire station sites were used with a 4 minute drive time as the cutoff to reach as many incidents as possible.


COVERED BY **2** STATIONS



COVERED BY 3 STATIONS

COVERED BY 4 STATIONS










640 possible sites.





25%

OF INCIDENTS ARE COVERED BY **2** STATIONS

**25%** 

of incidents are covered by  ${f 3}$  stations

0%

OF INCIDENTS ARE COVERED BY **4** STATIONS

#### **Ideal Station Location:**


The Ideal Station Location was calculated using ESRI's Location - Allocation Analysis tool. 640 possible fire station sites were used with a 4 minute drive time as the cutoff to reach as many incidents as possible.













**ERF** 



24% OF INCIDENTS ARE COVERED BY **2** STATIONS

**24**% OF INCIDENTS ARE

COVERED BY 3 STATIONS

0%

OF INCIDENTS ARE COVERED BY 4 STATIONS








# OF INCIDENTS ARE WITHIN THE

**4** MIN CATCHMENT







**ERF** 

**©** 

15%
OF INCIDENTS ARE COVERED BY 2 STATIONS

15%

OF INCIDENTS ARE COVERED BY 3 STATIONS

0%
OF INCIDENTS ARE
COVERED BY 4 STATIONS








# OF INCIDENTS ARE WITHIN THE

**4** MIN CATCHMENT







ERF ♠

**©** 

15%
OF INCIDENTS ARE COVERED BY 2 STATIONS

**15%** 

OF INCIDENTS ARE COVERED BY **3** STATIONS


0%


OF INCIDENTS ARE COVERED BY **4** STATIONS











Station 21 moved to 411 w Higgins and Station 22 moved to Ideal Identified Station Location Area





**4** MINUTE COVERAGE

AREA IN SQUARE MILES PERCENTAGE OF **TRA** 

Current **11.2** 

Proposed 12.2

RAGE

50% 54%



8 MINUTE COVERAGE

**AREA IN SQUARE MILES** 

20.7

PERCENTAGE OF TRA

92%

0.9 93




Catchments represent the area covered by drive time from the fire stations and are displayed at the four-minute and eight-minute increments.











## WITHIN 4 MIN CATCHMENT


	Ö	Ö	
	FIRE INCIDENTS	EMS INCIDENTS	OTHER INCIDENTS
Current	<b>77%</b>	83%	80%
Ideal	80%	88%	84%
Proposed	83%	86%	83%













## WITHIN 4 MIN CATCHMENT

	Ŏ	Ö	
	FIRE INCIDENTS	EMS INCIDENTS	OTHER INCIDENTS
Current	<b>77%</b>	83%	80%
Ideal	80%	88%	84%
Proposed	83%	84%	<b>82</b> %





Selected Auto Aid Stations
Barrington Countryside FPD Station 37
Barrington Countryside FPD Station 39
East Dundee and Countryside FPD Station 41

Elgin FD Station 1

Elgin FD Station 2

Elk Grove Village FD Station 10

Hanover Park FD Station 15

**Inverness FPD Station 36** 

Palatine FD Station 84

Rolling Meadows FD Station 16

Schaumburg FD Station 51

Schaumburg FD Station 52

Schaumburg FD Station 53

Schaumburg FD Station 54

Schaumburg FD Station 55

Streamwood FD Station 31


Streamwood FD Station 32

Streamwood FD Station 33

West Dundee FD Station 31









Map Layer Esri, HERE, Garmin, SafeGraph, GeoTechnologies, Inc, METI/NASA, USGS, EPA, NPS, USDA, Esri, HERE, Garmin, SafeGraph, FAO, METI/NASA, USGS, EPA, NPS


































































































Created By: Illinois Fire Chiefs Association
www.illinoisfirechiefs.org
Program Director
Dave Slivinski
(630) 201-6871
dslivinski@illinoisfirechiefs.org